

AD-A078 867

GAI CONSULTANTS INC MONROEVILLE PA

F/6 13/13

NATIONAL DAM INSPECTION PROGRAM. CHERRY RUN DAM (NDS I.D. NUMBE--ETC(U)

AUG 79 B M MIHALCIN

DACW31-79-C-0013


NL

UNCLASSIFIED

1 OF 2

AD  
A078867





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A



AD A 078867

OHIO RIVER BASIN  
CHERRY RUN, INDIANA COUNTY  
PENNSYLVANIA  
CHERRY RUN DAM

LEVEL

Number  
(NDS I.D. ~~PA~~ PA-00278  
PENNDER I.D. ~~No~~ 32-40)  
Number

6 PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM.

Cherry Run Dam, Ohio River Basin, Cherry Run,  
Indiana County, Pennsylvania. Phase I

Inspection Reports



ORIGINAL CONTAINS COLOR PLATES: ALL DDC  
REPRODUCTIONS WILL BE IN BLACK AND WHITE

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0013

PREPARED FOR

DEPARTMENT OF THE ARMY  
Baltimore District, Corps of Engineers  
Baltimore, Maryland 21203

10 Bernard M. Mihalcin  
PREPARED BY

Source LGAI CONSULTANTS, INC.  
570 BEATTY ROAD  
MONROEVILLE, PENNSYLVANIA 15146

11 AUGUST 1979

DDC FILE COPY

12/43

DDO  
RECEIVED  
JAN 7 1980  
A

35-7 1 063

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

A-23	
Special	

PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

ABSTRACT

Cherry Run Dam: NDI I.D. No. PA-00278

Owner: Rochester and Pittsburgh Coal  
Company

State Located: Pennsylvania (PennDER I.D. No. 32-40)

County Located: Indiana

Stream: Cherry Run

Inspection Date: 13 July 1979

Inspection Team: GAI Consultants, Inc.  
570 Beatty Road  
Monroeville, Pennsylvania 15146

*Excerpted from  
page 113*

Based on a visual inspection, maintenance of Cherry Run Dam appears minimal to non-existent and the facility is considered to be in poor condition.

Deficiencies noted by the inspection team included heavy overgrowth of the embankment sections (particularly to the right of the spillway), delamination of the spillway surface, cracking and misalignment of the spillway wingwalls, heavy overgrowth within the discharge channel, an inoperable outlet works, and no emergency warning system in effect.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility is considered to be the Probable Maximum Flood (PMF). Results of the hydrologic and hydraulic analysis indicate the facility will pass and/or store only 40 percent of the PMF prior to embankment overtopping. A breach analysis indicates that failure under less than 1/2 PMF conditions could lead to increased downstream damage and potential for loss of life. Thus, based on screening criteria provided in the recommended guidelines, the spillway is considered to be seriously inadequate and the facility unsafe, non-emergency.



Due to its poorly maintained condition and seriously inadequate spillway classification, the facility is considered unsafe. Failure is not considered imminent; however, it is recommended that the owner immediately develop a warning system to notify downstream residents should hazardous conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.


If it is the intent of the owner to reclaim and/or maintain useful function of the facility, it is recommended that the owner:


- a. Clear the embankment of all brush, trees, and high weeds to enable expedient visual evaluation, particularly of the right embankment section.
- b. Have the facility evaluated by a registered professional engineer experienced in the hydraulics and hydrology of dams and take remedial measures deemed necessary to make the facility hydraulically adequate. The study should also include an assessment of the structural integrity of the existing spillway structure and/or recommendations for remedial repairs to the concrete surfaces.
- c. Assess the condition of the outlet structures and restore the operability of the system to provide drawdown capabilities.
- d. Clear the downstream channel immediately adjacent to the stilling basin to provide unrestricted flow.
- e. Develop manuals of operation and maintenance to ensure continual proper care of the facility.

In lieu of items a through e above, it is recommended that the owner dispose of the facility in accordance with PennDER Division of Dam Safety regulations with due regard to the disposition of the impounded sediment.

GAI Consultants, Inc.

Approved by:

  
Bernard M. Mihalcin, P. E.

  
JAMES W. PECK  
Colonel, Corps of Engineers  
District Engineer



Date 28 August 1979

Date 18 Sep 79



Overview Photograph  
v

## TABLE OF CONTENTS

	<u>Page</u>
PREFACE . . . . .	i
ABSTRACT. . . . .	ii
OVERVIEW PHOTOGRAPH . . . . .	v
TABLE OF CONTENTS . . . . .	vi
SECTION 1 - GENERAL INFORMATION . . . . .	1
1.0 Authority . . . . .	1
1.1 Purpose . . . . .	1
1.2 Description of Project. . . . .	1
1.3 Pertinent Data. . . . .	2
SECTION 2 - ENGINEERING DATA. . . . .	5
2.1 Design. . . . .	5
2.2 Construction Records. . . . .	6
2.3 Operational Records . . . . .	7
2.4 Other Investigations. . . . .	7
2.5 Evaluation. . . . .	7
SECTION 3 - VISUAL INSPECTION . . . . .	8
3.1 Observations. . . . .	8
3.2 Evaluation. . . . .	9
SECTION 4 - OPERATIONAL PROCEDURES. . . . .	10
4.1 Normal Operating Procedure. . . . .	10
4.2 Maintenance of Dam. . . . .	10
4.3 Maintenance of Operating Facilities . . . . .	10
4.4 Warning System. . . . .	10
4.5 Evaluation. . . . .	10
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION . . . . .	11
5.1 Design Data . . . . .	11
5.2 Experience Data . . . . .	11
5.3 Visual Observations . . . . .	11
5.4 Method of Analysis. . . . .	11
5.5 Summary of Analysis . . . . .	11
5.6 Spillway Adequacy . . . . .	14
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY. . . . .	15
6.1 Visual Observations . . . . .	15
6.2 Design and Construction Techniques. . . . .	15
6.3 Past Performance. . . . .	15
6.4 Seismic Stability . . . . .	16
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES . . . . .	17
7.1 Dam Assessment. . . . .	17
7.2 Recommendations/Remedial Measures . . . . .	17



TABLE OF CONTENTS

APPENDIX A - CHECK LIST - ENGINEERING DATA  
APPENDIX B - CHECK LIST - VISUAL INSPECTION  
APPENDIX C - HYDROLOGY AND HYDRAULICS  
APPENDIX D - PHOTOGRAPHS  
APPENDIX E - GEOLOGY  
APPENDIX F - FIGURES  
APPENDIX G - REGIONAL VICINITY AND WATERSHED  
BOUNDARY MAPS

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM  
CHERRY RUN DAM  
NDI# PA-278, PENNDER# 32-40

SECTION 1  
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Cherry Run Dam is a zoned earth embankment with a central concrete corewall. The embankment measures approximately 430 feet long (including spillway) and 22 feet high. The facility is provided with an ogee-shaped concrete spillway located about 100 feet from the right abutment. The spillway crest is 132 feet long. A reinforced concrete control tower is located along the upstream embankment toe to the left of the spillway. Access to the tower is provided by a steel framed footbridge. The outlet works housed within the tower consists of a 12-inch diameter cast iron supply pipe and a 24-inch diameter cast iron blowoff pipe.

b. Location. Cherry Run Dam is located on Cherry Run in Center Township, Indiana County, Pennsylvania, about one mile west of Homer City, Pennsylvania. The dam, reservoir, and watershed are contained within the Indiana, Pennsylvania, U.S.G.S. 7.5 minute topographic quadrangle (see Appendix G). The coordinates of the dam are N 40° 32.5' and W 70° 10.8'.

c. Size Classification. Small (22 feet high, 390 acre-feet storage capacity at top of dam).

d. Hazard Classification. High (see Section 3.1.e).

e. Ownership. Rochester and Pittsburgh Coal Company  
655 Church Street  
Indiana, Pennsylvania 15701

f. Purpose. Formerly water supply for power production; currently used as a recreational facility for Rochester and Pittsburgh Coal Company personnel.

g. Historical Data. Information contained in PennDER files indicates that Cherry Run Dam was designed and constructed by the Rochester and Pittsburgh Coal and Iron Company in 1923. The construction history is well documented in memoranda, semi-monthly progress reports submitted by the owner's chief engineer, and about 70 construction photographs. The data indicate that the facility was constructed as designed. A major flood incident did, however, occur during construction, causing the embankment to be overtopped and resulting in the partial breaching of the embankment and destruction of the corewall to the right of the spillway.

Available data dated subsequent to completion of the facility pertains primarily to flashboard installation and reservoir siltation. No major deficiencies were recorded until 1971, when a PennDER inspection revealed that the facility was not being adequately maintained. Correspondence also indicates that the water supply function of the facility was discontinued in the early 1960's.

### 1.3 Pertinent Data.

a. Drainage Area (square miles). 11.4

b. Discharge at Dam Site.

Discharge Capacity of Outlet Conduit - Discharge curves are not available.

Discharge Capacity of Spillway at Maximum Pool ~ 5800 cfs (see Appendix C, Sheet 6).

c. Elevation (feet above mean sea level). The following elevations were obtained from available drawings and through field measurements based on the elevation of the spillway crest at 1025 feet.

Top of Dam	1030.0 (field)
Maximum Design Pool	Not known
Maximum Pool of Record	1028 (April, 1936)
Normal Pool	1025
Spillway Crest	1025
Upstream Inlet Invert	1009 (blowoff)
	1012 (supply)
Downstream Outlet Invert	1008 (blowoff)
	N/A (supply)

	Streambed at Dam Centerline	1009
	Maximum Tailwater	Not known
d.	<u>Reservoir Length (miles).</u>	
	Top of Dam	1.0
	Normal Pool	0.5
e.	<u>Storage (acre-feet).</u>	
	Top of Dam	390
	Normal Pool	185
	Design Surcharge	Not known
f.	<u>Reservoir Surface (acres).</u>	
	Top of Dam	50
	Normal Pool	31
	Maximum Design Pool	Not known
g.	<u>Dam.</u>	
	Type	Zoned earth with concrete corewall.
	Length	430 feet (including spillway).
	Height	22 feet; (field measured; crest to top of plunge pool overflow sill).
	Top Width	12 feet (field)
	Upstream Slope	2-1/2H:1V
	Downstream Slope	2H:1V
	Zoning	Two zones plus concrete corewall (see Figure 2). Selected material defined in specifications as "good quality of clay (not fire clay) mixed with some sand and gravel." Balance of embankment material defined as "earth, clay and gravel."

Impervious Core	Reinforced concrete wall extends from 1-foot below crest into rock (see Figure 2).
Cutoff	See "Impervious Core" above.
Grout Curtain	None indicated.
h. <u>Diversion Canal and Regulating Tunnels.</u>	None.
i. <u>Spillway.</u>	
Type	Uncontrolled concrete spillway with ogee-shaped crest located about 100 feet from the right abutment.
Crest Elevation	1025 feet
Crest Length	132 feet
j. <u>Outlet Works.</u>	
Type	Supply - 12-inch diameter cast iron pipe. Blowoff - 24-inch diameter cast iron pipe.
Length	100 feet (inlet to blowoff outlet; not including 80-foot extension).
Closure and Regulating Facilities	Flow through both conduits were controlled at the inlet end by sluice gates and/or gate valves located within a concrete control tower (see Figure 2). The mechanisms within the tower presently



appear nonfunctional  
and valves are reported  
to be closed (see Photo-  
graphs 3 and 4).

**Access**

Steel framed foot-  
bridge from crest  
(see Photograph 3).

## SECTION 2 ENGINEERING DATA

### 2.1 Design.

a. Design Data Availability and Sources. No design reports or calculations are available for any aspects of the facility. Design drawings are available from both PennDER and the owner's files. A 1923 report by PennDER predecessors discusses design features of the facility in detail.

b. Design Features.

1. Embankment. The contract drawings and specifications indicate the embankment is a zoned earth structure with a reinforced concrete core wall. The embankment is composed of two soil zones as shown on Figure 2. The selected material placed adjacent the upstream face of the core wall is described in the specifications as "a good quality of clay (not fire clay) mixed with some sand and gravel, with all large stones three inches in diameter or over, removed, (the material) shall be deposited in horizontal layers not over six inches thick, sprinkled and rolled with a spiked roller or tractor, and to be well rammed at all points which cannot be reached by roller". The balance of the embankment was to be constructed of "earth, clay and gravel placed in 6-inch layers, sprinkled and rolled (with) no stones over 2-1/2 inches to be allowed to remain in the fill."

The upstream slope is 2-1/2H:1V with a 12-inch thick layer of riprap protection extending from the crest to 4-1/2 feet below normal pool level. The downstream slope is 2H:1V and the crest width is 12 feet.

The corewall along the dam centerline is 12 inches wide at its top (one foot below the crest) and is battered to 2 feet in a depth of about 15 feet, below which a uniform thickness of 2 feet was maintained to rock. Both faces of the wall are reinforced by 5/8-inch square rods on 4-foot centers.

### 2. Appurtenant Structures.

a) Spillway. The spillway is an uncontrolled concrete weir with an ogee-shaped crest located about 100 feet from the right abutment. It consists of a 2-1/2-foot thick base slab underlying a massive ogee-shaped section flanked by sidewalls of varying thickness. Cutoffs on the upstream and downstream sides of the spillway extend into

the hard clay upon which the slab is founded. The spillway was incised below the existing stream channel to provide a 7-foot deep stilling basin approximately 20 feet in length (see Figure 3).

The slab and spillway face are reinforced. The massive weir section was built of "cyclopean masonry, using not over 30 percent of plums, and balance being 1-3-5 concrete, except that the wearing surface should be finished with 1-2-4 concrete". The slab and wingwalls were built of "1-3-5 concrete and finished with 1-2-4 concrete".

b. Outlet Works. The outlet works consist of a reinforced concrete riser, 7 feet by 9 feet in plan, and is located on the upstream toe adjacent to the left wing-wall of the spillway. A 24-inch sluice gate was provided to control flow into the tower on the upstream side. Outflow was provided by a 12-inch diameter cast iron supply line controlled with a gate valve within the riser and a 24-inch diameter cast iron blowoff line controlled by a 24-inch diameter sluice gate also within the riser (see Figure 2). A concrete cutoff collar was placed around both pipes within the upstream section of the embankment.

c. Specific Design Data and Criteria.

1. Hydrology and Hydraulics. Although no calculations are available, correspondence contained in PennDER files indicate that prevailing spillway design criteria were considered. A 1923 report by PennDER predecessors states "the capacity of the spillway, 132 feet long and 5 feet deep, is 5,725 cubic feet per second, or 475 cubic feet per second per square mile. With a depth of 4 feet and a freeboard of 1-foot, the capacity is 4,100 cubic feet per second, or 340 cubic feet per second per square mile, which is the runoff shown on our curves for maximum runoff for 12 square miles".

2. Embankment. No design data other than material specifications are available.

3. Appurtenant Structures. Other than concrete mixes, no data are available.

2.2 Construction Records.

Contract drawings, specifications, construction progress reports and about 70 construction photographs are available in PennDER files.



### 2.3 Operational Records.

No records of present day-to-day operation of the facility are maintained.

### 2.4 Other Investigations.

The owner has conducted soundings to assess the available storage; however, records are not available. The owner estimated that the average depth of water in the reservoir in 1957 was between 4 to 8 feet.

### 2.5 Evaluation.

PennDER files contain excellent historical accounts of the facility particularly of its construction. The data are considered adequate to make a reasonable Phase I assessment of the facility.

### SECTION 3 VISUAL INSPECTION

#### 3.1 Observations

a. General. The general appearance of the facility suggests that it is minimally maintained and in poor condition.

b. Embankment. The visual inspection indicated that the main embankment to the left of the spillway was in fair condition. No seepage or slumping was observed although the slopes are overgrown with high weeds, grass, and some shrubs. The riprap appeared to be in fair condition and functional.

The right embankment section was observed to be in poor condition being heavily overgrown with brush and trees to the extent that its boundaries are barely discernible. Swamplike conditions were observed near the embankment-abutment contact (possibly due to poor surface drainage) while an erosion gully was noted at what appeared to be the downstream embankment toe-natural ground contact.

#### c. Appurtenant Structures.

1. Spillway. The spillway is considered to be in poor condition suffering from general concrete deterioration. The overflow weir (reportedly gunnited in the early 1950's) is extensively cracked and has begun delaminating (peeling) near its center (see Photographs 8 and 9). The wingwalls are extensively spalled, cracked and noticeably misaligned (see Photographs 9 and 10). The downstream channel is overgrown with shrubs and trees which could restrict flow and cause high tailwater conditions.

2. Outlet Works. The outlet works at Cherry Run Dam is in poor condition. The access bridge to the control riser is hazardous with missing and/or deteriorated planking (see Photograph 3). The control tower is open (see Photograph 4) and all control mechanisms are missing. Probing with the level rod indicated the control riser may be surrounded by substantial amounts of sediment.

The discharge end of the cast iron blowoff line was found to be partially obstructed and not connected to the terra-cotta pipe extension (Photograph 5) which terminates in the stream about 120 feet from the downstream toe (see Photograph 6). The pump house structure was observed to be dilapidated and the apparent subject of extensive vandalism.

Operability of any of the valves within the pump house is doubtful.

d. Reservoir Area. The area immediately surrounding the reservoir is characterized by moderate to steep, heavily forested slopes. The watershed, however, is composed primarily (about 75 percent) of agricultural lands (see Appendix G, Watershed Boundary Map). Years of farmland runoff has resulted in substantial sedimentation of the Cherry Run Reservoir. The owner estimates that the average depth of water in the reservoir is currently about 4 to 8 feet.

e. Downstream Channel. The channel downstream of Cherry Run Dam is contained within a gently sloped, broad, tree and brush filled valley. Normal flow is confined in a small meandering stream about 25 feet wide and 5 feet in depth. Four residential dwellings and a power plant are located along the stream within 1-1/2 miles of the dam. At least three of the residential dwellings are sufficiently close to the stream that they could suffer damage with possible loss of life from high flows associated with a dam failure (see Photograph 12). Thus, the hazard classification of the facility is considered to be "high".

### 3.2 Evaluation.

The overall appearance of the facility suggests it to be in poor condition. Maintenance of the embankment and appurtenances appears minimal to non-existent. The reservoir is heavily sedimented although the owner had installed two sedimentation ponds in the 1940's at the upstream end of the reservoir presumably to control further siltation of the facility. Major deficiencies include heavy overgrowth of the embankment, cracking and delamination of the spillway concrete and an apparent non-functional outlet works.

Operability of any of the valves within the pump house is doubtful.

d. Reservoir Area. The area immediately surrounding the reservoir is characterized by moderate to steep, heavily forested slopes. The watershed, however, is composed primarily (about 75 percent) of agricultural lands (see Appendix G, Watershed Boundary Map). Years of farmland runoff has resulted in substantial sedimentation of the Cherry Run Reservoir. The owner estimates that the average depth of water in the reservoir is currently about 4 to 8 feet.

e. Downstream Channel. The channel downstream of Cherry Run Dam is contained within a gently sloped, broad, tree and brush filled valley. Normal flow is confined in a small meandering stream about 25 feet wide and 5 feet in depth. Four residential dwellings and a power plant are located along the stream within 1-1/2 miles of the dam. At least three of the residential dwellings are sufficiently close to the stream that they could suffer damage with possible loss of life from high flows associated with a dam failure (see Photograph 12). Thus, the hazard classification of the facility is considered to be "high".

### 3.2 Evaluation.

The overall appearance of the facility suggests it to be in poor condition. Maintenance of the embankment and appurtenances appears minimal to non-existent. The reservoir is heavily sedimented although the owner had installed two sedimentation ponds in the 1940's at the upstream end of the reservoir presumably to control further siltation of the facility. Major deficiencies include heavy overgrowth of the embankment, cracking and delamination of the spillway concrete and an apparent non-functional outlet works.



## SECTION 4 OPERATIONAL PROCEDURES

### 4.1 Normal Operating Procedure.

Cherry Run Dam is essentially a self-regulating facility with excess inflow discharged over the uncontrolled concrete spillway. No formal operating manuals are associated with the facility.

### 4.2 Maintenance of Dam.

Visual inspection indicates that maintenance of the dam is presently minimal to non-existent. Records in PennDER files indicate some maintenance to the embankment was performed in 1972. No formal maintenance manual is in existence.

### 4.3 Maintenance of Operating Facilities.

Visual inspection indicates that the operating facilities are presently not maintained and appear to be non-functional. There is no maintenance manual available.

### 4.4 Warning System.

Discussions with Rochester and Pittsburgh Coal Company personnel indicate that there is no formal warning system in effect for the facility.

### 4.5 Evaluation.

There are no operating or maintenance manuals available for the facility. Maintenance of the dam and appurtenances appears to be minimal to non-existent. There is no warning system in effect for the notification of downstream residents in the event emergency conditions develop.

## SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

### 5.1 Design Data

No formal design reports or calculations are available; however, correspondence contained in PennDER files indicates that the spillway, as designed, would pass, with 1-foot of freeboard, "4,100 cubic feet per second, or 340 cubic feet per second per square mile, which is the runoff shown on our curves for maximum runoff for 12 square miles". The statement implies that the spillway was adequately designed for the criteria then in effect.

### 5.2 Experience Data.

Daily records of reservoir levels and/or spillway discharge are not available.

### 5.3 Visual Observations.

The visual inspection indicated that the spillway system is in poor condition. Deficiencies include delamination of the overflow surface (applied in early 1950), cracking and misalignment of the wingwalls, and dense overgrowth of the stream channel immediately below the stilling basin. Due to its poor condition, it is possible that structural damage could occur under high flows.

### 5.4 Method of Analysis.

The facility has been analyzed in accordance with the procedures and guidelines established by the U. S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U. S. Army, Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly outlined in the preface contained in Appendix C.

### 5.5 Summary of Analysis.

a. Spillway Design Flood (SDF). In accordance with procedures and guidelines contained in the National Guidelines

for Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Cherry Run Dam ranges between the 1/2 PMF (Probable Maximum Flood) and the PMF. This classification is based on the relative size of the dam (small), and the potential hazard of dam failure to downstream developments (high). Due to the high potential for damage to the downstream residences and structures, the SDF for this facility is considered to be the PMF.

b. Results of Analysis. Cherry Run Dam was evaluated under normal operating conditions. That is, the reservoir was initially at its normal pool or spillway elevation of approximately 1025 feet (MSL), with the low level blowoff and supply lines closed. Although most of the available storage volume behind the dam is sediment filled, it was assumed that the sediment is in a liquid state. The spillway is a free overfall, concrete, ogee-shaped weir structure.

Downstream routing information (discharge vs storage data) for the selected valley and channel cross-sections of concern was computed via the HEC-2 Computer Program. The necessary downstream routing was done under the assumption that the stream was dry prior to the inflow of the dam outflow. All pertinent engineering calculations relative to the evaluation of this facility are provided in Appendix C.

Overtopping analysis (using the Modified HEC-1 Computer Program) indicated that the discharge/storage capacity of Cherry Run Dam can accommodate only about 40 percent of the PMF (SDF) prior to the overtopping of the embankment (Appendix C, Summary Input/Output Sheets, Sheet K). The low top of dam was inundated by depths of water of 0.6 and 3.0 feet under the 1/2 PMF and PMF events, respectively (Summary Input/Output Sheets, Sheet K). Therefore, since the SDF for this facility is the PMF, Cherry Run Dam has a high potential for overtopping and, thus, for breaching under floods of less than PMF magnitude.

Since Cherry Run Dam cannot safely handle a flood of at least 1/2 PMF magnitude, the possibility of embankment failure under floods of 1/2 PMF intensity or less was investigated (in accordance with ETL-1110-2-234). Several feasible alternatives were analyzed since it is difficult, if not impossible, to determine exactly how or if a specific dam will fail. The major concern of the breaching evaluations is with the impact of the various breach discharges on increasing downstream water surface elevations above those to be expected if breaching did not occur.

The Modified HEC-1 Computer Program was used for the breaching analysis with the assumption that the breaching of a dam would begin once its reservoir's water level reached the low top of dam elevation.

Two sets of breach geometry were evaluated for the Cherry Run Dam for each of two failure times (Appendix C, Sheet 12). The two sets of breach sections chosen were considered to be the minimum and maximum probable failure sections. The two failure times (total time for each breach section to reach its final dimensions), under which the two breach sections were investigated, were assumed to be a rapid time (0.5 hours) and a prolonged time (4.0 hours), so that a range of this most sensitive variable might be examined. In addition, an average or more probable set of breach conditions was analyzed, with a failure time of 1.0 hour.

The peak breach outflows (resulting from a 0.41 PMF overtopping) ranged from about 5970 cfs for the minimum section - prolonged fail time scheme, to about 18410 cfs for the maximum section - minimum fail time scheme (Appendix C, Sheet 14). The outflow from the average breach condition was about 11630 cfs, compared to the non-breach 0.41 PMF peak facility outflow of about 5960 cfs (Summary Input/Output Sheets, Sheet K). The water surface elevation corresponding to the non-breach 0.41 PMF peak discharge at a section (Section 2) located 2640 feet downstream from the dam was approximately 1013.5 feet (MSL); and approximately 1012.1 feet (MSL) at a section (Section 3) located 4000 feet downstream from the dam (Summary Input/Output Sheets, Sheet K). The water surface elevations corresponding to the average condition peak breach outflow at the two above-mentioned downstream sections were 1016.1 feet (MSL) and 1014.4 feet (MSL), respectively (Appendix C Sheet 15). The approximate elevations of the first two residences located at Section 2 are about 1017 feet (MSL); while the approximate elevation of the house located at Section 3 is about 1009 feet (MSL). Therefore, the increase in the water surface at Section 2, caused by the failure of Cherry Run Dam, was about 2.6 feet, with the breach water surface just below the damage levels of the two houses. The increase in the water surface at Section 3, caused by the failure of the dam was about 2.3 feet, with the breach water surface above the damage level of the home (although the structure would experience some flooding even without breaching).

Since the embankment is provided with a concrete core-wall, a near instantaneous type of failure (under 0.41 PMF base conditions) was also considered (Appendix C, Sheet 12). The peak breach outflow was about 20720 cfs, which resulted in water surface elevations of 1017.5 feet (MSL) and 1015.1



feet (MSL) at downstream Sections 2 and 3, respectively (Appendix C, Sheet 15). The increase in the water surface at Section 2, caused by the near instantaneous breach of Cherry Run Dam, was about 4.0 feet, with the breach water surface above the damage levels of both houses. The increase in the water surface at Section 3, caused by the near instantaneous failure of the dam, was about 3.0 feet, with the breach water surface again above the damage level of the house. In addition, it can be surmised that the same consequences as expected from an instantaneous type of failure can also occur during an embankment breach under average conditions, if the base flood is somewhat larger than the 0.41 PMF.

The consequences of dam failure can be better envisioned if not only the increase in the height of the floodwave is considered, but, also the great increase in the momentum of the larger and probably swifter moving volume of water. Therefore, the failure of Cherry Run Dam is quite possible and will most probably lead to increased property damage and loss of life in the downstream regions.

#### 5.6 Spillway Adequacy.

As presented previously, under existing conditions Cherry Run Dam can accommodate only about 40 percent of the PMF (the SDF) prior to embankment overtopping. Should a 0.41 PMF or larger event occur, the dam could be overtopped and could possibly fail, endangering the residences in the immediate downstream area. Therefore, the spillway of Cherry Run Dam is considered to be seriously inadequate.

SECTION 6  
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations, the main embankment section to the left of the spillway is in fair condition. The only apparent deficiency noted was the lack of regular maintenance resulting in an overgrowth of weeds, high grass, and some shrubs.

The embankment section to the right of the spillway is considered to be in poor condition. It is heavily overgrown with shrubs and trees and appears to be poorly drained, particularly at the embankment-abutment contact. Some erosion at the embankment-natural slope interface was also noted.

b. Appurtenant Structures.

1. Spillway. Visual observations indicate the spillway is in poor structural condition. Deficiencies include delamination of the overflow surface, structural cracking and misalignment of the wingwalls and a partially obstructed downstream channel. Due to its poor condition, it is possible that structural damage could occur under high flows.

2. Outlet Works. The outlet works was observed to be in poor condition and is presumably inoperable. Field measurements indicate that sediment levels may be above the sluice gate that controls inflow to the riser.

6.2 Design and Construction Techniques.

Correspondence, specifications, contract drawings, construction progress reports and construction photographs indicate that the facility was adequately engineered and constructed. Construction problems were openly discussed and resolved with PennDER predecessors.

6.3 Past Performance.

According to available correspondence and discussions with representatives of the owner, the facility has performed satisfactorily since construction in 1923. Reservoir siltation has been a persistent problem and is apparently due to the extensive agricultural use of the watershed.

#### 6.4 Seismic Stability.

The dam is located within Seismic Zone No. 1 and is subject to minor earthquake induced dynamic forces. As the facility appears well constructed and sufficiently stable, it is believed that it can withstand the expected dynamic forces; however, no calculations and/or investigations were performed to confirm this opinion.

SECTION 7  
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment

a. Safety. The visual inspection suggests the facility is in poor condition.

The size classification of the facility is small and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility is considered to be the Probable Maximum Flood (PMF). Results of the hydrologic and hydraulic analysis indicate the facility will pass and/or store only about 40 percent of the PMF prior to embankment overtopping. A breach analysis indicates that failure under less than 1/2 PMF conditions could lead to increased downstream damage and potential for loss of life. Thus, based on screening criteria contained in the recommended guidelines, the spillway is considered to be seriously inadequate and the facility unsafe, non-emergency.

Deficiencies noted by the inspection team included heavy overgrowth of the embankment sections (particularly to the right of the spillway), delamination of the spillway surface, cracking and misalignment of the spillway wingwalls, heavy overgrowth within the discharge channel, inoperable outlet works, and no emergency warning system in effect.

b. Adequacy of Information. The available data are considered sufficient to make a reasonable Phase I assessment of the facility.

c. Urgency. Due to its poorly maintained condition and seriously inadequate spillway, implementation of a warning system, along with studies and/or remedial action as recommended below should be immediately undertaken.

d. Necessity for Additional Investigations. Additional investigations are considered necessary and are listed in Section 7.2 below.

7.2 Recommendations/Remedial Measures.

Due to its poorly maintained condition and seriously inadequate spillway classification, the facility is considered unsafe. Failure is not considered imminent; however, it is recommended that the owner immediately develop a warning

8 system to notify downstream residents in the event hazardous conditions develop. Included in the plan should be provisions for around-the-clock surveillance of the facility during periods of unusually heavy precipitation.

If it is the intent of the owner to reclaim and/or maintain useful function of the facility, it is recommended that the owner:

a. Clear the embankment of all brush, trees, and high weeds to enable expedient visual evaluation, particularly of the right embankment section.

b. Have the facility evaluated by a registered professional engineer experienced in the hydraulics and hydrology of dams and take remedial measures deemed necessary to make the facility hydraulically adequate. The study should also include an assessment of the structural integrity of the existing spillway structure and/or recommendations for remedial repairs to the concrete surfaces.

c. Assess the condition of the outlet structures and restore the operability of the system to provide drawdown capabilities.

d. Clear the downstream channel immediately adjacent to the stilling basin to provide unrestricted flow.

e. Develop manuals of operation and maintenance to ensure continual proper care of the facility.

In lieu of items a through e above, it is recommended that the owner dispose of the facility in accordance with PennDER Division of Dam Safety regulations with due regard to the disposition of the impounded sediment.



APPENDIX A  
CHECK LIST - ENGINEERING DATA

CHECK LIST  
ENGINEERING DATA  
PHASE I

NAME OF DAM: Cherry Run Dam  
NDI#: PA-278 PENNDR#: 32-40

PAGE 1 OF 5

ITEM	REMARKS	NDI# PA - 278
PERSONS INTERVIEWED AND TITLE	Rochester and Pittsburgh Coal Company James Schaffer, Chief Engineer Ed Sokol, Engineer James G. Wiley, Chief of Maintenance	
REGIONAL VICINITY MAP	See Appendix G (U.S.G.S. 7.5 minute topographic quadrangle, Indiana, PA)	
CONSTRUCTION HISTORY	Designed and constructed by Rochester and Pittsburgh Coal and Iron Company.  Detailed correspondence, about 70 photograph, specifications, and progress drawings concerning the construction of the facility are available in PennDR files (see Section 1.2.g.)	
AVAILABLE DRAWINGS	Numerous design, construction progress, and proposed change drawings are available in PennDR files. Representative drawings are provided in Appendix F.	
TYPICAL DAM SECTIONS	See Appendix F, Figure 2.	
OUTLETS: PLAN DETAILS DISCHARGE RATINGS	See Appendix F, Figures 2, 4, 5 and 6.  Not available.	

ITEM	REMARKS	NDI# PA - 278
SPILLWAY: PLAN SECTION DETAILS	See Appendix F, Figure 4. See Appendix F, Figure 3. See Appendix F, Figure 3.	
OPERATING EQUIPMENT PLANS AND DETAILS	See Appendix F, Figures 2 and 6.	
DESIGN REPORTS	None available.	
GEOLOGY REPORTS	None available.	
DESIGN COMPUTATIONS: HYDROLOGY AND HYDRAULICS STABILITY ANALYSES SEEPAGE ANALYSES	None available.	
MATERIAL INVESTIGATIONS: BORING RECORDS LABORATORY TESTING FIELD TESTING	Boring information discussed in correspondence available in PennDER files. Some subsurface information given on Figure 3, Appendix F. No laboratory or field testing information available.	



## ENGINEERING DATA (CONTINUED)

PAGE 3 5

ITEM	REMARKS	NDI# PA - 278
BORROW SOURCES	Not known. Possibly from within reservoir.	
POST CONSTRUCTION DAM SURVEYS	None.	
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	<p>An in-house evaluation of the reservoir bottom, in 1957, concluded that the maximum reservoir depth was about 8 feet, and the overall average depth was about 4 feet. Data not available.</p> <p>Reservoir bottom soundings were taken between 1968 and 1970 to determine silt level. Data not available.</p>	
HIGH POOL RECORDS	None presently available. Water level records were previously kept when facility was still used for water supply and power generation. Water was reported by the owner to have risen high enough to fail the flashboards on occasion.	
MONITORING SYSTEMS	None.	
MODIFICATIONS	Flashboards were added to the spillway shortly after construction, but have been removed since the 1960's. Provisions for flashboards still exist. Spillway weir and wingwalls were gunited in the early 1950's. A spillway was reported by the owner to have been cut into the right abutment, possibly at the time of the guniting, however, it must have been filled in since that time.	

## ENGINEERING DATA (CONTINUED)

PAGE 4 OF 5

ITEM	REMARKS	NDIN	PA 278
PRIOR ACCIDENTS OR FAILURES	None since facility was completed. However, during construction, the entire embankment section to the right of the spillway failed. (PennDER files contain photographs of the breached dam).		
MAINTENANCE: RECORDS MANUAL	When the facility was still used for water supply and power generation, a full time dam tender performed routine and other necessary maintenance. Presently, no formal maintenance and/or operation program exists. Maintenance and operation manuals are not available.		
OPERATION: RECORDS MANUAL	See "Maintenance" above.		
OPERATIONAL PROCEDURES	No formal procedures. Facility is no longer used for its original purpose.		
WARNING SYSTEM AND/OR COMMUNICATION FACILITIES	None.		
MISCELLANEOUS	Present function of dam is reported by the owner to be that of a limited recreational facility for select company personnel. Facility is not open to the public.		

CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

NDI ID # PA-278  
PENN DER ID # 32-40  
PAGE 5 OF 5

SIZE OF DRAINAGE AREA: 11.4 square miles  
ELEVATION TOP NORMAL POOL: 1025 STORAGE CAPACITY: 185 acre-feet  
ELEVATION TOP FLOOD CONTROL POOL: -- STORAGE CAPACITY: --  
ELEVATION MAXIMUM DESIGN POOL: -- STORAGE CAPACITY: --  
ELEVATION TOP DAM: 1030 STORAGE CAPACITY: 390 acre-feet

SPILLWAY DATA

CREST ELEVATION: 1025  
TYPE: Free overall, concrete, ogee-shaped weir structure  
WIDTH: 132 feet  
LENGTH: N/A  
SPILLOVER LOCATION: Near center of embankment  
NUMBER AND TYPE OF GATES: None

OUTLET WORKS

TYPE: 24-inch diameter C.I.P. blowoff; 12-inch diameter C.I.P. supply  
LOCATION: Control tower located just to left of spillway; outlet  
located about 75 feet downstream from embankment.  
ENTRANCE INVERTS: 1009  
EXIT INVERTS: 1008  
EMERGENCY DRAWDOWN FACILITIES: Inlet of outlet conduit is supposedly  
equipped with a sluice gate which is  
presently non-functional.

HYDROMETEOROLOGICAL GAGES

TYPE: None  
LOCATION: --  
RECORDS: --

MAXIMUM NON-DAMAGING DISCHARGE: Not known

APPENDIX B  
CHECK LIST - VISUAL INSPECTION

CHECK LIST  
VISUAL INSPECTION  
PHASE 1

PAGE 1 OF 8

NAME OF DAM Cherry Run Dam STATE Pennsylvania COUNTY Indiana  
NDI# PA - 278 PENNIDER# 32-40  
TYPE OF DAM Zoned Earth SIZE Small HAZARD CATEGORY High  
DATE(S) INSPECTION 13 July 1979 WEATHER Hot and Humid TEMPERATURE 80 @ 10:00 a.m.  
POOL ELEVATION AT TIME OF INSPECTION 1025 M.S.L.  
TAILWATER AT TIME OF INSPECTION N/A M.S.L.

INSPECTION PERSONNEL	OWNER REPRESENTATIVES	OTHERS
<u>B. M. Mihalcin</u>	<u>Rochester &amp; Pittsburgh Coal Company</u>	
<u>W. J. Veon</u>	<u>Ed Sokol</u>	
<u>D. L. Bonk</u>	<u>Jim Wiley</u>	

RECORDED BY D. L. Bonk



EMBANKMENT

PAGE 2 OF 8

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 278
SURFACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Slight erosion at right abutment-embankment contact. Possibly the result of poor drainage conditions.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal - good. Vertical - slightly lower near spillway wingwalls.	
RIPRAP FAILURES	Hand placed cut stone riprap with some mortared facing.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Embankment - spillway abutments; good condition. Embankment - valley abutments; left abutment good condition; right abutment is poorly drained, minor erosion observed.	

# EMBANKMENT

PAGE 3 OF 8

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 278
DAMP AREAS IRREGULAR VEGETATION (LUSH OR DEAD PLANTS)	No damp or wet areas due to seepage observed along downstream embankment face. Right abutment is poorly drained. Embankment left of spillway is overgrown with high weeds and brush. Embankment right of spillway is heavily overgrown with trees and brush.	
ANY NOTICEABLE SEEPAGE	None through embankment.	
STAFF GAGE AND RECORDER	None.	
DRAINS	None.	

## OUTLET WORKS

ITEM	OBSERVATIONS AND/OR REMARKS	NDH PA - 278
INTAKE STRUCTURE	Control tower dilapidated and non-functional. Access bridge hazardous.	
OUTLET CONDUIT (CRACKING AND SPALLING OF CONCRETE SURFACES)	24-inch diameter cast iron pipe; outlet end observed to the left of the stream about 75 feet downstream of the embankment. 80-foot long terra-cotta pipe extends further downstream. Terra-cotta and cast iron pipes are presently not connected.	
OUTLET STRUCTURE	Dilapidated tile block pump house located about 75 feet downstream of the embankment left of the spillway. Basement level is flooded while the interior has been thoroughly vandalized. Operability of the valves is doubtful.	
OUTLET CHANNEL	Discharge is diverted into Cherry Run which, immediately below the dam, is a small gently sloping stream at the base of a heavily overgrown valley	
GATE(S) AND OPERATIONAL EQUIPMENT	Gates and valves in control tower appear to be non-functional with gate control mechanisms missing. Gates and valves within pump house may be functional, but, have not been operated since 1964.	

## EMERGENCY SPILLWAY

PAGE 5 OF 8

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 278
TYPE AND CONDITION	Free overfall, concrete, ogee-shaped weir structure in poor condition.	
APPROACH CHANNEL	Not applicable.	
SPILLWAY CHANNEL AND SIDEWALLS	Sidewalls in poor condition exhibiting extensive cracking, spalling, and bulging. The left sidewall has a major structural crack on its upstream end, and the end has rotated somewhat.	
STILLING BASIN PLUNGE POOL	Good condition.	
DISCHARGE CHANNEL	See "Outlet Channel", page 4 of 8.	
BRIDGE AND PIERS	None.	
EMERGENCY GATES	None.	

SERVICE SPILLWAY

PAGE 6 OF 8

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 278
TYPE AND CONDITION	N/A	
APPROACH CHANNEL	N/A	
OUTLET STRUCTURE	N/A	
DISCHARGE CHANNEL	N/A	



## INSTRUMENTATION

ITEM	OBSERVATIONS AND/OR REMARKS	NDJH PA - 278
MONUMENTATION SURVEYS	None.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHERS		

# RESERVOIR AREA AND DOWNSTREAM CHANNEL

PAGE 8 OF 8

ITEM	OBSERVATIONS AND/OR REMARKS	NDI# PA - 278
SLOPES: RESERVOIR	Moderate to steep, and heavily forested in immediate vicinity of dam. Total watershed is primarily agricultural (about 75 percent).	
SEDIMENTATION	Reservoir displays signs of heavy sedimentation. Dense vegetal growth within the reservoir about 600 feet or so upstream from the embankment.	
DOWNSTREAM CHANNEL (OBSTRUCTIONS, DEBRIS, ETC.)	Cherry Run flows beneath 3 bridge structures prior to its confluence with Two Lick Creek. The first bridge is located about 3900 feet downstream from the dam.	
SLOPES: CHANNEL VALLEY	Broad wooded valley with steep, partially wooded, confining slopes for 3900 feet downstream from the dam.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	Three homes that could possibly be affected by the floodwave resulting from a breach in the embankment are located within the first 3900 feet downstream from the dam. Estimated population is about 9 or 10.	

APPENDIX C  
HYDROLOGY AND HYDRAULICS

## PREFACE

The modified HEC-1 program is capable of performing two basic types of hydrologic analyses: 1) the evaluation of the overtopping potential of the dam; and 2) the estimation of the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. Briefly, the computational procedures typically used in the dam overtopping analysis are as follows:

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.
- c. Routing of the outflow hydrograph(s) from the reservoir to desired downstream locations. The results provide the peak discharge(s), time(s) of the peak discharge(s), and the maximum stage(s) of each routed hydrograph at the downstream end of each reach.

The evaluation of the hydrologic-hydraulic consequences resulting from an assumed structural failure (breach) of the dam is typically performed as shown below.

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir.
- c. Development of a failure hydrograph(s) based on specified breach criteria and normal reservoir outflow.
- d. Routing of the failure hydrograph(s) to desired downstream locations. The results provide estimates of the peak discharge(s), time(s) to peak and maximum water surface elevations of failure hydrographs for each location.

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
BY WJV DATE 7-31-79 PROJ. NO. 73-617-278  
CHKD. BY DLB DATE 8-4-79 SHEET NO. 1 OF 15



Engineers • Geologists • Planners  
Environmental Specialists

## DAM STATISTICS

HEIGHT OF DAM  $\approx$  22 FT (FIELD MEASURED)  
(MEASURED FROM INVERT OF OUTLET)

MAXIMUM POOL STORAGE CAPACITY  $\approx$  390 AC-FT (FROM HEC-1)  
@ TOP OF DAM

NORMAL POOL STORAGE CAPACITY  $\approx$  185 AC-FT (SEE NOTE 1)  
(DESIGN)

DRAINAGE AREA  $\approx$  11.4 SQ. MI.

PLANIMETERED OFF USGS  
7.5 MINUTE INDIANA,  
PA. QUAD

NOTE 1: DESIGN NORMAL STORAGE CAPACITY OBTAINED FROM "REPORT UPON THE APPLICATION OF THE ROCHESTER AND PITTSBURGH COAL AND IRON COMPANY (FOR CONSTRUCTION OF A DAM ACROSS CHERRY RUN, ABOUT ONE MILE WEST OF HOMER LICK IN CENTER TOWNSHIP, INDIANA COUNTY, PENNSYLVANIA", DATED 1923, AS FOUND IN PFUNDELL FILES. THE ACTUAL REPORTED VALUE WAS 60 MILLION GALLONS. HOWEVER, MOST OF THE AVAILABLE STORAGE VOLUME IS PRESENTLY SEDIMENT FILLED.

## DAM CLASSIFICATION

DAM SIZE - SMALL (REF 1, TABLE 1)

HAZARD CLASSIFICATION - HIGH (FIELD OBSERVATION)

REQUIRED SDF -  $\frac{1}{2}$  FMF TO FMF (REF 1, TABLE 3)



SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
BY WIV DATE 7-31-79 PROJ. NO. 73-617-278  
CHKD. BY DLB DATE 8-4-79 SHEET NO. 2 OF 15



Engineers • Geologists • Planners  
Environmental Specialists

### HYDROGRAPH PARAMETERS

LENGTH OF LONGEST WATERCOURSE  $\approx 6.9$  MI

$L_{CA} \approx 3.4$  MI (MEASURED ALONG THE LONGEST WATERCOURSE  
FROM THE DAM TO THE CENTROID OF THE BASIN)

NOTE 2: VALUES OF  $L$  AND  $L_{CA}$  ARE MEASURED FROM THE  
USGS 7.5 MINUTE INDIANA, PA QUAD. ALL  
VARIABLES ARE DEFINED IN REF 2, IN THE  
SECTION ENTITLED "SNYDER SYNTHETIC  
UNIT HYDROGRAPH".

$$C_t \approx 1.6$$

$$C_p \approx 0.45$$

[ SUPPLIED BY COE, ZONE 24  
OHIO RIVER BASIN ]

$$T_p = \text{SNYDER'S STANDARD LAG} \approx 1.6 (L \times L_{CA})^{0.3}$$

$$\therefore T_p \approx 1.6 (6.9 \times 3.4)^{0.3} \approx 4.11 \text{ HRS}$$

### RESERVOIR SURFACE AREAS

SURFACE AREA (SA) @ NORMAL POOL EL 1025.0 FT  $\approx 31.2$  AC

NOTE 3: NORMAL POOL EL 1025.0 FT OBTAINED FROM APPENDIX  
F, FIGURE 2. NORMAL POOL SA OBTAINED FROM  
THE REFERENCE GIVEN IN NOTE 1, SHEET 1.

SA @ EL 1040  $\approx 88.4$  AC (PLANIMETERED OFF INDIANA, PA QUAD)

LOW TOP OF DAM ELEVATION  $\approx 1030.0$  FT (FIELD MEASURED)

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
BY WJV DATE 7-31-79 PROJ. NO. 78-617-278  
CHKD. BY DLB DATE 8-4-79 SHEET NO. 3 OF 15



RATE OF SA INCREASE PER FOOT OF RESERVOIR RISE  $\Rightarrow$

$$\Delta SA / \Delta H \approx (38.1 - 31.2) / (1040.0 - 1025.0) \approx 3.8 \frac{AC}{FT}$$

$$SA @ \text{LOW TOP OF DAM EL } 1030.0 \approx 31.2 AC + [(3.8 \frac{AC}{FT})(1030 - 1025)] \\ \approx 50.2 AC$$

### RESERVOIR ELEVATION @ "0" STORAGE

NORMAL POOL VOLUME  $\approx \frac{1}{3} HA \approx 195 AC\text{-FT}$  (CONIC METHOD)

SA @ NORMAL POOL EL 1025.0  $\approx 31.2 AC$

$$\therefore H \approx 3(195 AC\text{-FT}) / 31.2 AC \approx 17.8 FT$$

ZERO VOLUME ELEVATION  $\approx 1025.0 - 17.8 FT \approx 1007.2 FT$

NOTE 4: ALTHOUGH THE ACTUAL DESIGN MINIMUM RESERVOIR ELEVATION APPEARS TO BE ABOUT EL 1009.5 (FIG 2), IN ORDER TO COMPUTE AN ELEVATION-STORAGE RELATIONSHIP AND STILL MAINTAIN A STORAGE OF 195 AC-FT @ EL 1025.0, THE ABOVE "0" STORAGE ELEVATION MUST BE INPUT INTO THE HEC-1 PROGRAM.

### RESERVOIR ELEVATION-STORAGE RELATIONSHIP

COMPUTED INTERNALLY BY THE HEC-1 PROGRAM BASED ON THE GIVEN ELEVATION VS SURFACE AREA INFORMATION (SEE SUMMARY INPUT/OUTPUT SHEETS).

NOTE 5: ALTHOUGH MOST OF THE AVAILABLE DESIGN STORAGE VOLUME IS PRESENTLY SEDIMENT FILLED, IT IS FELT THAT THE SEDIMENT HAS NOT CONSOLIDATED TO A POINT

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
BY WJV DATE 7-31-79 PROJ. NO. 78-G17-278  
CHKD. BY DLB DATE 8-4-79 SHEET NO. 4 OF 15



WHERE IT CAN RESIST FLOW. THEREFORE, THE  
ENTIRE DESIGN STORAGE VOLUME CAN STILL POTENTIALLY  
FLOW DOWNSTREAM IF RELEASED VIA A DAM BREACH.

### PM P CALCULATIONS

- APPROXIMATE RAINFALL INDEX = 24 IN (REF 3, FIG 1)  
(CORRESPONDING TO A DURATION OF 24 HR  
AND AN AREA OF 200 SQMI, LOCATED  
IN SOUTHWESTERN PENNSYLVANIA)
- DEPTH-AREA-DURATION ZONE # 7 (REF 3, FIG 1)
- STORM WILL BE CENTERED OVER THE 11.4 SQMI BASIN  
WITH A DEPTH-DURATION RELATIONSHIP OF:

DURATION (HR)	PERCENT OF INDEX RAINFALL (%)
6	101
12	119
24	129
48	139

- HOPKINSON FACTOR (ADJUSTMENT FOR BASIN SHAPE AS WELL  
AS FOR THE LESSER LIKELIHOOD OF A SEVERE STORM CENTERING  
OVER A SMALLER BASIN) CORRESPONDING TO A DA  $\approx$  11.4 SQMI  
 $\Rightarrow$  0.805 (FROM HEC-1 OUTPUT)

SUBJECT DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJV

DATE 7-31-79

PROJ. NO. 72-617-279

CHKD. BY DLB

DATE 8-4-79


SHEET NO. 5 OF 15

**gai**  
CONSULTANTS, I


Engineers • Geologists • Planners  
Environmental Specialists

## SPILLWAY CAPACITY

- PROFILE OF SPILLWAY : (NOT TO SCALE)  
(FROM FIELD MEASUREMENTS AND OBSERVATION, AND FIG 3)



- CROSS-SECTION OF SPILLWAY : (NOT TO SCALE)  
(FROM FIELD MEASUREMENTS AND OBSERVATIONS, AND FIG 3 AND 4)



SECTION TAKEN LOOKING UPSTREAM TOWARD SPILLWAY

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
BY WJV DATE 7-31-79 PROJ. NO. 78-617-278  
CHKD. BY DLB DATE 8-4-79 SHEET NO. 6 OF 15



- THE SPILLWAY IS A FREE OVERFALL, CONCRETE, OGEE-SHAPED WEIR STRUCTURE. DISCHARGE OVER A WEIR IS DEFINED BY THE RELATIONSHIP:

$$Q = CLH^{3/2} \quad (\text{REF 4, 573})$$

WHERE  $Q$  = DISCHARGE IN CFS;  
 $L$  = LENGTH OF WEIR CREST  $\approx 132$  FT;  
 $H$  = HEIGHT OF RESERVOIR ABOVE SPILLWAY CREST  
 $\approx 5.0$  FT PRIOR TO EMBANKMENT OVERTOPPING;  
 $C$  = DISCHARGE COEFFICIENT =  $f$  (DESIGN HEAD, ACTUAL HEAD, SLOPE OF US FACE, DS APRON EFFECTS, AND SUBMERGENCE).

- DETERMINATION OF "C":

FIELD MEASURED FOREBAY DEPTH ( $P$ )  $\approx 9.0$  FT  
ASSUMED DESIGN HEAD ( $H_0$ )  $\approx 5.0$  FT

$$\Rightarrow P/H_0 \approx 9.0/5.0 \approx 1.8 \Rightarrow C_0 \approx 3.93 \quad (\text{REF 4 PG 57})$$

SINCE THE SLOPE OF US WEIR FACE ADJUSTMENT DOES NOT APPLY, AND DETRIMENTAL DS APRON EFFECTS AND SUBMERGENCE ARE NOT LIKELY  $\Rightarrow C \approx 3.93$

- APPROACH CHANNEL LOSSES ARE NEGLIGIBLE DUE TO THE LARGE SPILLWAY DEPTH

$$\therefore \text{SPILLWAY CAPACITY} = Q \approx (3.93)(132\text{ FT})(5.0\text{ FT})^{3/2}$$

$$Q \approx 5800 \text{ CFS}$$

( $Q \approx 5899$  AS COMPUTED BY HEC-1, DUE TO COMPUTER ROUNDING)



SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 7-31-79 PROJ. NO. 73-617-278  
 CHKD. BY DLB DATE 8-4-79 SHEET NO. 7 OF 15



### SPILLWAY RATING CURVE

COMPUTED INTERNALLY BY HEC-1 VIA THE OGEE RATING CURVE ROUTINE. THE OGEE ROUTINE COMPUTES DISCHARGES IN A MANNER SIMILAR TO THAT OUTLINED ON SHEET 6, BASED ON THE INPUT INFORMATION: DESIGN HEAD  $\approx 5.0$ , APRON ELEVATION  $\approx 1009$  FT (INITIAL TW ELEVATION, FIG 3), APRON WIDTH  $\approx 132$  FT, APPROACH CHANNEL LOSS @ DESIGN HEAD  $\approx 0.0$  FT, AND FOREBAY DEPTH  $\approx 9.0$  FT.

### EMBANKMENT RATING CURVE


- COMPUTED INTERNALLY BY HEC-1 VIA THE ASSUMPTION THAT CRITICAL DEPTH ON THE CREST CONTROLS POSSIBLE OVERTOPPING FLOWS. THE CREST PROFILE IS REPRESENTED BY A SERIES OF TRAPEZIODS (SEE SUMMARY INPUT/OUTPUT SHEETS FOR RATING INFORMATION)
- INPUT INFORMATION: (BASED ON FIELD MEASUREMENTS)

RESERVOIR ELEVATION (FT)	HEIGHT ABOVE CREST (FT)	INUNDATED CREST LENGTH (FT)
1030.0	0	25
1030.1	0.1	70
1030.3	0.3	105
1030.4	0.4	120
1030.8	0.8	195
1030.9	0.9	270
1031.1	1.1	305
1032.0	2.0	340
1033.0	3.0	375
1034.0	4.0	410

BASED PARTIALLY  
 ON ESTIMATED  
 ABUTMENT SECTIONS  
 OF  $\approx 170$  FT IV  
 FROM DISSEMINARY MAP

# DOWNSTREAM ROUTING SECTION


SHEET B OF 15






# ADDITIONAL DOWN-STREAM H.C. 2 SECTIONS

SHEET 9 OF 15



# ADDITIONAL DATA FROM FIELD SECTIONS

SHEET 10 OF 15





SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-4-79 PROJ. NO. 78-617-278  
 CHKD. BY DLB DATE 8-4-79 SHEET NO. 11 OF 15



## DOWNSTREAM ROUTING RELATIONSHIPS

DOWNSTREAM ROUTING INFORMATION (DISCHARGE VS STORAGE RELATIONSHIPS) WAS COMPUTED VIA THE HEC-2 WATER SURFACE PROFILE COMPUTER PROGRAM\*. HEC-2 CALCULATES BACKWATER CURVES BY THE STANDARD STEP METHOD (REF 7, PG 274-280) BASED ON VALLEY AND CHANNEL CROSS-SECTION DATA. THE SPECIFIC CROSS-SECTION INFORMATION USED IS GIVEN ON SHEETS 9 TO 10. THE VARIOUS PROFILES WERE INITIATED VIA THE SLOPE-AREA METHOD (REF 7, PG 146-148) APPLIED TO SECTION 6. THE CALCULATIONS THEN PROCEEDED UPSTREAM TO SECTIONS 5 AND 4, AND AND THEN TO THE BRIDGE @ SECTION 3. THE BRIDGE WAS MODELLED BY THE "SPECIAL BRIDGE" ROUTINE OF THE PROGRAM. COMPUTATIONS THEN PROCEEDED TO SECTION 2, AND FINALLY TO SECTION 1 AT THE TOE OF THE DAM. SINCE THE RESIDENCES OF CONCERN ARE LOCATED AT SECTIONS 2 AND 3, ONLY THESE SECTIONS WILL BE CONSIDERED IN THE DOWNSTREAM ROUTING. DISCHARGE VS STORAGE RELATIONSHIPS FOR SECTIONS 2 AND 3 ARE (FROM HEC-2 OUTPUT OF SHEETS D AND E, SUMMARY INPUT/OUTPUT SHEETS):

SECTION 2			
DISCHARGE (CFS)	STORAGE (AC-FT)	DISCHARGE (CFS)	STORAGE (AC-FT)
0	0	17800	247
400	5.7	22900	283
1400	13.5	28000	323
2500	40.0	32000	354
5000	89.1	40000	411
7600	132	45000	444
10200	165	49000	470
12700	201		

SECTION 3			
DISCHARGE (CFS)	STORAGE (AC-FT)	DISCHARGE (CFS)	STORAGE (AC-FT)
0	0	17800	175
400	3.0	22900	203
1400	10.3	28000	229
2500	23.5	32000	251
5000	74.9	40000	298
7600	106	45000	327
10200	129	49000	349
12700	145		

© SEE SHEET E, SUMMARY INPUT/OUTPUT SHEETS

\* HEC-2 WATER SURFACE PROFILES (USER'S MANUAL), HYDROLOGIC ENGINEERING CENTER, U.S. ARMY CORPS OF ENGINEERS, DAITCH CAMPUS, NOV 1977




SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-4-79 PROJ. NO. 78-617-273  
 CHKD. BY DLB DATE 8-4-79 SHEET NO. 12 OF 15

**gai**  
 CONSULTANTS, INC.  
 Engineers • Geologists • Planners  
 Environmental Specialists

## BREACH ASSUMPTIONS

### - TYPICAL BREACH SECTION:



### - HEC-1 - DAM BREACHING ANALYSIS INPUTS:

(BREACHING WILL COMMENCE WHEN THE RESERVOIR LEVEL REACHES THE TOP OF DAM ELEVATION)

PLAN NUMBER AND COMMENT	BREACH BOTTOM WIDTH (FT)	MAX BREACH DEPTH (FT)	SECTION SIDESLOPES	* BREACH TIME (HRS)	WSEL @ TIME OF FAILURE (FT)
① MIN BREACH SECT; MIN FAIL TIME	0	18	1H TO 1V	0.5	1030.0
② MAX BREACH SECT; MIN FAIL TIME	300	18	3H TO 1V	0.5	1030.0
③ MIN BREACH SECT; MAX FAIL TIME	0	18	1H TO 1V	4.0	1030.0
④ MAX BREACH SECT; MAX FAIL TIME	300	18	3H TO 1V	4.0	1030.0
⑤ AVERAGE POSSIBLE CONDITIONS	150	18	1H TO 1V	1.0	1030.0
⑥ INSTANTANEOUS FAILURE	100	18	1H TO 1V	0.25	1030.0

\* BREACH TIME = TOTAL TIME NECESSARY TO REACH FINAL BREACH DIMENSIONS

SUBJECT DAM SAFETY INSPECTIONCHERRY RUN DAMBY WJV DATE 3-4-79 PROJ. NO. 73-6-17-273CHKD. BY DLE DATE 3-4-79 SHEET NO. 13 OF 15Engineers • Geologists • Planners  
Environmental Specialists

- THE BREACH ASSUMPTIONS LISTED ON SHEET 11 ARE BASED SOMEWHAT ON INFORMATION CONCERNING EARTH DAM BREACHING PROVIDED BY THE COE, BALTIMORE DISTRICT; AND ALSO ON THE PHYSICAL CONSTRAINTS OF THE DAM AND SURROUNDING TERRAIN:

CONSTRAINT	VALUE
- HEIGHT OF DAM	≈ 22 FT (FIELD MEASURED)
- AVERAGE HEIGHT OF EMBANKMENT	≈ 13 FT (FIG 7)
- EMBANKMENT CREST LENGTH:	
LEFT OF SPWY	≈ 200 FT
RIGHT OF SPWY	≈ 100 FT
TOTAL	≈ 300 FT
	} FIELD MEASURED
- VALLEY BOTTOM WIDTH	≈ 300 FT (FIG 7)
- VALLEY SIDESLOPES ADJACENT TO DAM:	
RIGHT WALL	3H TO 1V
LEFT WALL	3H TO 1V
	} FIG. 7

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-4-79 PROJ. NO. 73-617-273  
 CHKD. BY DLB DATE 8-4-79 SHEET NO. 14 OF 15



# HEC-1 - DAM BREACHING ANALYSIS OUTPUT :

## RESERVOIR DATA

### UNDER 0.41 PMF BASE FLOW CONDITIONS -

* PLAN NUMBER	VARIABLE BREACH BOTTOM WIDTH (FT)	ACTUAL MAX FLOW DURING FAIL TIME (CFS)	CORRESPONDING TIME OF FLOW (HR)	EXTRAPOLATED HEC-1 ROUTED MAX FLOW DURING FAIL TIME (CFS)	CORRESPONDING TIME OF FLOW (HR)	ACTUAL PEAK FLOW THROUGH DAM (CFS)	CORRESPONDING TIME OF PEAK (HR)	TIME OF INITIAL BREACH (HR)
①	0	8032	44.25	8032	44.25	8032	44.25	43.75
②	300	18410	44.11	17127	44.00	18410	44.11	43.75
③	0	5967	44.05	5966	44.00	5967	44.08	43.75
④	300	7213	44.58	7196	44.50	7213	44.58	43.75
⑤	150	11628	44.56	11459	44.50	11628	44.56	43.75
⑥	100	20722	44.00	20722	44.00	20722	44.00	43.75

\* SEE TABLE ON SHEET 12

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-4-79 PROJ. NO. 79-617-273  
 CHKD. BY DLB DATE 8-4-79 SHEET NO. 15 OF 15



# HEC-1 - DAM BREACHING ANALYSIS OUTPUT :

## DOWNSTREAM ROUTING DATA

### UNDER 0.41 PMF BASE FLOW CONDITIONS -

1. PLAN NUMBER	VARIABLE BREACH BOTTOM WIDTH (FT)	OUTPUT @ SECTION 2 LOCATED 2640 FT DS FROM DAM		OUTPUT @ SECTION 3 LOCATED 4000 FT DS FROM DAM		4. Δ ELEV (FT)
		PEAK FLOW (CFS)	WSEL 2. (FT)	WSEL 3. (FT)	WSEL 2. (FT)	
①	0	7274	1014.4	1013.5	1012.9	+0.8
②	300	14765	1017.4	1013.5	1014.9	+2.8
③	0	5952	1013.5	1013.5	1012.1	+0.0
④	300	7153	1014.3	1013.5	1012.9	+0.8
⑤	150	10840	1016.1	1013.5	1014.4	+2.3
⑥	100	14980	1017.5	1013.5	1015.1	+3.0

1. SEE TABLE ON SHEET 12
2. WATER SURFACE ELEVATIONS CORRESPONDING TO BREACH FLOWS AS INTERPOLATED FROM SHEETS D AND E, SUMMARY INPUT / OUTPUT SHEETS
3. BASE FLOW ELEVATIONS CORRESPONDING TO THE PEAK 0.41 PMF AS INTERPOLATED FROM SHEETS D AND E, SUMMARY INPUT / OUTPUT SHEETS (FROM SHEET K)
4. Δ ELEV = CORRESPONDING WSEL - WSEL W/O BREACH



SUBJECT

DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJV

DATE 8-6-79

PROJ. NO. 78-617-278

CHKD. BY DLB

DATE 8-6-79

SHEET NO. A OF M

Engineers • Geologists • Planners  
Environmental Specialists

## SUMMARY INPUT/OUTPUT SHEETS

DAM SAFETY INSPECTION - DOWNSTREAM ROUTING INFORMATION													
12 START CALCULATIONS VIA SURGE-AREA METHOD, MODEL BRIDGE VIA SPECIAL BRIDGE													
13 CHERRY RUN BELOW CHERRY RUN DAM													
J1	ICHECK	IRG	2.	0.	0.	0.	0.	0.002000	0.0	0.	0.	996.000	0.0
J2	NPROF	IPLOT	PREVS	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	CHWIN	ITRACE
J3	VARIABLE	CODES	FOR	SUMMARY	PRINTOUT								
J4	LEAF	10RSEC											
J5	LEAF	10RSEC											
*****REQUESTED SECTION NUMBERS*****													
IC	0.070	-10.000	0.0	0.030	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
OF	14.000	400.000	1400.000	0.000	2500.000	5000.000	7600.000	10200.000	12700.000	17800.000	22900.000	0.0	0.0
CI	24000.000	32000.000	40000.000	45000.000	45000.000	49000.000	0.0	0.0	0.0	0.0	0.0	0.0	0.0
X1	6.000	10.000	750.000	785.000	835.000	1000.000	1000.000	996.000	750.000	993.000	155.000	0.0	0.0
GR	1040.000	0.0	1020.000	550.000	350.000	1000.000	700.000	996.000	1300.000	1040.000	1350.000	0.0	0.0
GR	993.000	780.000	996.000	785.000	835.000	1000.000	1050.000	1020.000	0.0	0.0	0.0	0.0	0.0
NC	0.070	0.080	0.030	0.300	0.300	0.500	0.0	0.0	0.0	0.0	0.0	0.0	0.0
X1	5.000	10.000	800.000	835.000	835.000	1300.000	650.000	1000.000	0.0	0.0	0.0	0.0	0.0
GR	1040.000	0.0	1020.000	350.000	350.000	1000.000	400.000	996.000	800.000	995.000	805.000	0.0	0.0
GR	993.000	830.000	996.000	835.000	835.000	1000.000	950.000	1020.000	1050.000	1040.000	1150.000	0.0	0.0
NC	0.070	0.070	0.030	0.300	0.300	0.500	0.0	0.0	0.0	0.0	0.0	0.0	0.0
X1	4.000	10.000	1230.000	1265.000	1265.000	1000.000	1000.000	1000.000	0.0	0.0	0.0	0.0	0.0
GR	1040.000	0.0	1020.000	950.000	950.000	1000.000	1150.000	1000.000	1230.000	997.000	1235.000	0.0	0.0
GR	993.000	1260.000	1000.000	1265.000	1265.000	1000.000	1300.000	1020.000	1500.000	1040.000	1600.000	0.0	0.0
NC	0.070	0.070	0.030	0.300	0.300	0.500	0.0	0.0	0.0	0.0	0.0	0.0	0.0
X1	3.200	10.000	1030.000	1065.000	1065.000	750.000	1050.000	950.000	0.0	0.0	0.0	0.0	0.0
GR	1040.000	0.0	1020.000	450.000	450.000	1011.000	830.000	1002.000	1030.000	999.000	1030.000	0.0	0.0
GR	993.000	1065.000	1005.000	1065.000	1065.000	1011.000	1140.000	1020.000	1300.000	1040.000	1400.000	0.0	0.0
NC	0.070	0.070	0.030	0.300	0.300	0.700	0.0	0.0	0.0	0.0	0.0	0.0	0.0
X1	3.100	0.0	0.0	0.0	0.0	50.000	50.000	50.000	0.0	0.0	0.0	0.0	0.0
GR	1040.000	0.0	0.0	0.0	0.0	0.0	0.0	0.0	1010.000	1010.000	1030.000	0.0	0.0
GR	993.000	0.070	0.030	0.300	0.300	0.400	0.0	0.0	0.0	0.0	0.0	0.0	0.0
NC	0.070	0.070	0.030	0.300	0.300	0.400	0.0	0.0	0.0	0.0	0.0	0.0	0.0



# DAM SAFETY INSPECTION

CHERRY RUN DAM

Y WJY

DATE \_\_\_\_\_

8-6-79

PROJ. NO.

79-617-278

CHKD. BY DLB

DATE \_\_\_\_\_

B-6-7

SHEET NO.

B OF M



Engineers • Geologists • Planners  
Environmental Specialists

[illegible]

SUMMARY PRINCIPLES			CUMULATIVE						
SECNO	ALCH	ELMIN	DISCHARGE Q	ELEVATION CNSPL	CRI-S	EG	VCH	AREA	VOLUME
SETTIN	0.0	993.00	400.00	996.14	0.0	996.41	4.22	95.62	0.0
	0.0	993.00	1400.00	998.59	0.0	999.12	6.41	444.56	0.0
	0.0	993.00	7500.00	1000.00	0.0	1000.61	7.52	860.00	0.0
	0.0	994.00	5000.00	1001.88	0.0	1002.56	8.93	1552.87	0.0
	0.0	993.00	1003.37	1003.37	0.0	1004.12	9.94	2154.63	0.0
2.000	0.0	993.00	10200.00	1004.59	0.0	1005.41	10.81	2677.47	0.0
	0.0	993.00	12700.00	1005.66	0.0	1006.52	11.46	3159.96	0.0
	0.0	993.00	17800.00	1007.53	0.0	1008.50	12.60	4061.42	0.0
	0.0	993.00	22900.00	1009.14	0.0	1010.20	13.55	4892.37	0.0
	0.0	993.00	28000.00	1010.58	0.0	1011.72	14.34	5684.04	0.0
DS FROM	0.0	993.00	32000.00	1011.63	0.0	1012.82	14.90	6281.30	0.0
	0.0	993.00	40000.00	1013.51	0.0	1014.81	15.51	7412.33	0.0
	0.0	993.00	45000.00	1014.59	0.0	1015.96	16.46	8093.84	0.0
	0.0	993.00	49000.00	1015.40	0.0	1016.82	16.89	8621.27	0.0
	0.0	993.00			0.0				
DAM	0.0	993.00			0.0				
	0.0	993.00			0.0				
	0.0	993.00			0.0				
	0.0	993.00			0.0				
	0.0	993.00			0.0				

SUBJECT

DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJY

DATE

8-6-79

PROJ. NO.

73-617-278CHKD. BY DLB

DATE

8-6-79

SHEET NO.

COF MEngineers • Geologists • Planners  
Environmental SpecialistsCUMULATIVE  
VOLUME

SECTION	ALICH	ELMIN	DISCHARGE Q	ELEVATION CHSEL	CRIBS	EG	VCH	AREA	VOL
SECTION @ ~ 6000 FT DS FROM DAM	5.000	1000.00	995.00	400.00	998.16	998.43	4.18	98.73	2.23
	5.000	1000.00	995.00	1400.00	1000.44	1000.62	4.44	920.30	16.24
	5.000	1000.00	995.00	2500.00	1001.76	1001.89	4.36	1654.64	29.59
	5.000	1000.00	995.00	5000.00	1003.65	1003.79	5.00	2738.18	49.89
	5.000	1000.00	995.00	7600.00	1005.19	1005.34	5.55	3628.54	66.96
	5.000	1000.00	995.00	10200.00	1006.47	1006.65	6.04	4392.54	81.61
	5.000	1000.00	995.00	12700.00	1007.58	1007.78	6.45	5059.58	94.65
	5.000	1000.00	995.00	17800.00	1009.54	1009.78	7.18	6262.99	118.44
	5.000	1000.00	995.00	22900.00	1011.23	1011.51	7.82	7323.86	139.74
	5.000	1000.00	995.00	28000.00	1012.74	1013.06	8.39	8291.11	159.46
SECTION @ ~ 5000 FT DS FROM DAM	5.000	1000.00	995.00	32000.00	1013.83	1014.17	8.81	8998.61	174.06
	5.000	1000.00	995.00	40000.00	1015.80	1016.20	9.57	10300.04	201.19
	5.000	1000.00	995.00	45000.00	1016.92	1017.36	10.01	11057.70	217.19
	5.000	1000.00	995.00	49000.00	1017.77	1018.24	10.35	11634.60	229.46
	4.000	1000.00	997.00	400.00	1000.15	1000.41	4.16	112.09	4.65
	4.000	1000.00	997.00	1400.00	1001.82	1002.33	6.67	395.20	31.34
	4.000	1000.00	997.00	2500.00	1002.77	1003.53	8.56	563.47	55.28
	4.000	1000.00	997.00	5000.00	1004.49	1005.56	10.91	967.35	92.37
	4.000	1000.00	997.00	7600.00	1005.92	1007.20	12.44	1330.26	123.87
	4.000	1000.00	997.00	10200.00	1007.14	1008.58	13.57	1672.41	151.23
SECTION @ ~ 5000 FT DS FROM DAM	4.000	1000.00	997.00	12700.00	1008.19	1009.76	14.45	1988.74	175.55
	4.000	1000.00	997.00	17800.00	1010.67	1011.84	15.83	2615.40	220.35
	4.000	1000.00	997.00	22900.00	1011.71	1013.63	16.90	3218.98	260.75
	4.000	1000.00	997.00	28000.00	1013.19	1015.22	17.77	3808.26	298.35
	4.000	1000.00	997.00	32000.00	1014.26	1016.37	18.34	4266.49	326.32
	4.000	1000.00	997.00	40000.00	1016.20	1018.45	19.37	5149.40	378.52
	4.000	1000.00	997.00	45000.00	1017.32	1019.64	19.92	5690.21	409.43
	4.000	1000.00	997.00	49000.00	1018.16	1020.53	20.33	6115.16	433.20
	3.200	950.00	999.00	400.00	1001.96	1002.19	3.85	103.78	6.99
	3.200	950.00	999.00	1400.00	1004.32	1005.07	7.12	245.71	37.91
SECTION @ ~ 50 FT DS FROM BRIDGE (LOCATED @ ~ 4000 FT DS FROM DAM)	3.200	950.00	999.00	2500.00	1005.80	1006.95	9.18	401.91	65.22
	3.200	950.00	999.00	5000.00	1007.87	1009.66	12.21	745.31	109.47
	3.200	950.00	999.00	7600.00	1009.38	1011.55	14.18	1088.11	147.94
	3.200	950.00	999.00	10200.00	1010.60	1013.02	15.56	1423.58	182.01
	3.200	950.00	999.00	12700.00	1011.80	1014.06	15.76	1812.48	213.31
	3.200	950.00	999.00	17800.00	1013.41	1015.75	16.98	2465.63	270.80
	3.200	950.00	999.00	22900.00	1014.97	1017.16	17.34	3246.10	324.89
	3.200	950.00	999.00	28000.00	1016.37	1018.42	17.51	4071.87	376.47
	3.200	950.00	999.00	32000.00	1017.55	1019.40	17.20	4859.79	416.73
	3.200	950.00	999.00	40000.00	1019.70	1021.26	16.67	6510.99	493.89
SECTION @ ~ 4000 FT DS FROM DAM	3.200	950.00	999.00	45000.00	1020.92	1022.32	16.24	7561.86	540.47
	3.200	950.00	999.00	49000.00	1021.84	1023.13	15.95	8372.16	576.38

SUBJECT

DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJV

DATE

8-6-79

PROJ. NO.

79-617-273CHKD. BY DLB

DATE

8-6-79

SHEET NO.

D OF MEngineers • Geologists • Planners  
Environmental SpecialistsCUMULATIVE  
VOLUME

SECTION	ALCH	ELEV	U	CUSFL	CRKWS	EG	VCH	AREA	VOL.
DS	50.00	999.00	400.00	1002.06	0.0	1002.28	3.75	106.80	7.11
FACE	50.00	999.00	1400.00	1004.45	0.0	1005.28	7.33	190.99	38.16
OF	50.00	999.00	2500.00	1005.85	0.0	1007.54	10.42	239.84	65.59
BRIDGE	50.00	999.00	5000.00	1007.58	1007.58	1011.88	16.65	300.36	110.07
	50.00	999.00	7600.00	1011.26	1010.14	1012.29	10.36	1630.51	149.50
	50.00	999.00	10200.00	1013.04	0.0	1013.92	10.31	2301.17	184.15
	50.00	999.00	12700.00	1013.81	0.0	1014.83	11.39	2653.45	215.87
	50.00	999.00	17800.00	1015.28	0.0	1016.47	12.91	3418.03	274.18
	50.00	999.00	22900.00	1016.34	0.0	1017.73	14.37	4056.28	329.08
	50.00	999.00	28000.00	1017.34	0.0	1018.85	15.45	4716.00	381.52
	50.00	999.00	32000.00	1018.16	0.0	1019.70	15.97	5296.69	422.56
	50.00	999.00	40000.00	1020.03	0.0	1021.45	16.06	6790.29	501.53
	50.00	999.00	45000.00	1021.18	0.0	1022.48	15.76	7789.41	599.28
	50.00	999.00	49000.00	1022.04	0.0	1023.27	15.60	8559.48	586.10
	35.00	999.00	400.00	1002.13	0.0	1002.34	3.65	109.49	7.20
	35.00	999.00	1400.00	1004.62	0.0	1005.40	7.12	196.57	38.32
	35.00	999.00	2500.00	1006.22	0.0	1007.74	9.90	252.58	65.79
	35.00	999.00	5000.00	1011.46	0.0	1011.88	6.56	1702.05	110.87
	35.00	999.00	7600.00	1013.20	0.0	1013.66	7.49	2373.18	151.11
	35.00	999.00	10200.00	1014.20	0.0	1014.77	8.63	2845.91	186.22
	35.00	999.00	12700.00	1014.73	0.0	1015.46	9.95	3118.82	218.19
	35.00	999.00	17800.00	1015.71	0.0	1016.74	12.15	3672.17	277.07
	35.00	999.00	22900.00	1016.51	0.0	1017.82	14.05	4164.36	332.39
	35.00	999.00	28000.00	1017.34	0.0	1018.85	15.42	4724.98	385.31
	35.00	999.00	32000.00	1018.17	0.0	1019.70	15.93	5313.50	426.82
	35.00	999.00	40000.00	1020.03	0.0	1021.45	16.05	6796.48	506.99
	35.00	999.00	45000.00	1021.18	0.0	1022.48	15.76	7791.19	555.54
	35.00	999.00	49000.00	1022.04	0.0	1023.27	15.60	8559.41	592.98
	50.00	999.00	400.00	1002.21	0.0	1002.41	3.57	112.64	7.32
	50.00	999.00	1400.00	1005.18	0.0	1005.67	5.86	328.88	38.62
	50.00	999.00	2500.00	1007.95	0.0	1008.38	6.02	760.47	66.37
	50.00	999.00	5000.00	1011.54	0.0	1011.93	6.49	1720.76	112.84
	50.00	999.00	7600.00	1013.26	0.0	1013.71	7.41	2401.88	153.85
	50.00	999.00	10200.00	1014.27	0.0	1014.83	8.55	2877.77	189.50
	50.00	999.00	12700.00	1014.84	0.0	1015.54	9.79	3176.63	221.81
	50.00	999.00	17800.00	1015.89	0.0	1016.86	11.85	3761.06	281.30
	50.00	999.00	22900.00	1016.79	0.0	1017.99	13.55	4345.58	337.27
	50.00	999.00	28000.00	1017.70	0.0	1019.05	14.76	4973.43	390.87
	50.00	999.00	32000.00	1018.52	0.0	1019.91	15.27	5576.34	433.07
	50.00	999.00	40000.00	1020.32	0.0	1021.63	15.49	7043.67	514.93
	50.00	999.00	45000.00	1021.40	0.0	1022.62	15.38	7981.86	564.59
	50.00	999.00	49000.00	1022.23	0.0	1023.40	15.29	8775.13	602.90

US FACE  
OF BRIDGE  
@ 2ND  
STRUCTURE  
LOCATIONSECTION  
@  
25 FT US  
FROM BRIDGE  
(OR 315 FT  
DS FROM  
DAM)

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-6-79 PROJ. NO. 78-617-278  
 CHKD. BY DLB DATE 8-6-79 SHEET NO. E OF M



SECTION	ABCH	ELATE	DISCHARGE	ELEVATION	CRIMS	EG	VCH	AREA	CUMULATIVE VOLUME
SECTION @ 2645 FT DS FROM DAM @ 1st STRUCTURE LOCATION	2.000	1360.00	400.00	1005.35	0.0	1005.85	5.70	70.18	10.18
	2.000	1360.00	1400.00	1008.17	1007.06	1008.94	7.23	309.16	48.58
	2.000	1360.00	2500.00	1009.87	0.0	1010.44	7.06	1030.28	94.32
	2.000	1360.00	5000.00	1012.62	0.0	1013.06	5.71	2949.10	185.74
	2.000	1360.00	7600.00	1014.61	0.0	1014.84	6.09	4227.16	257.34
	2.000	1360.00	10200.00	1015.85	0.0	1016.11	6.69	5168.59	315.11
	2.000	1360.00	12700.00	1016.74	0.0	1017.05	7.33	5878.00	363.16
	2.000	1360.00	17800.00	1018.34	0.0	1018.71	8.40	7183.55	452.47
	2.000	1360.00	22900.00	1019.58	0.0	1020.12	9.31	8319.31	534.98
	2.000	1360.00	28000.00	1020.88	0.0	1021.37	10.09	9354.81	614.55
	2.000	1360.00	32000.00	1021.74	0.0	1022.28	10.64	10120.95	678.12
	2.000	1360.00	40000.00	1023.33	0.0	1023.95	11.61	11558.78	805.33
DS TIE OF DAM	2.000	1360.00	45000.00	1024.21	0.0	1024.88	12.19	12371.30	842.32
	2.000	1360.00	49000.00	1024.89	0.0	1025.60	12.61	13012.28	942.23
	1.000	2640.00	400.00	1011.44	0.0	1011.62	3.39	118.03	15.88
	1.000	2640.00	1400.00	1014.15	0.0	1014.65	5.84	373.22	67.11
	1.000	2640.00	2500.00	1015.24	0.0	1016.15	8.17	602.83	134.30
	1.000	2640.00	5000.00	1016.33	1016.33	1018.46	12.96	912.39	274.88
	1.000	2640.00	7600.00	1018.00	1018.00	1020.28	14.30	1526.26	349.46
	1.000	2640.00	10200.00	1019.13	1019.13	1021.68	15.73	2046.41	480.59
	1.000	2640.00	12700.00	1020.64	1020.64	1022.72	15.11	2852.05	563.89
	1.000	2640.00	17800.00	1021.91	1021.91	1024.35	17.19	3572.97	699.52
	1.000	2640.00	22900.00	1022.66	1022.66	1025.75	19.84	4005.32	817.67
	1.000	2640.00	28000.00	1023.86	0.0	1027.00	20.70	4716.78	937.52
	1.000	2640.00	32000.00	1024.80	0.0	1027.93	21.17	5282.50	1031.87
	1.000	2640.00	40000.00	1026.49	0.0	1029.68	22.11	6334.16	1216.66
	1.000	2640.00	45000.00	1027.43	0.0	1030.70	22.73	6936.55	1326.41
	1.000	2640.00	49000.00	1028.16	0.0	1031.48	23.21	7402.45	1411.96

NOTE: STORAGE VOLUMES @ SECTION 2 (BETWEEN DAM AND SECTION 2) WERE OBTAINED BY SUBTRACTING THE CUMULATIVE VOLUME VALUES OF SECTION 1.0 FROM THOSE OF SECTION 2.0. STORAGE VOLUMES @ SECTION 3 (BETWEEN SECTION 2 AND SECTION 3) WERE OBTAINED BY SUBTRACTING THE CUMULATIVE VOLUME VALUES OF SECTION 2.0 FROM THOSE OF SECTION 3.0.



SUBJECT

DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJV

DATE

8-6-79

PROJ. NO.

79-617-278

CHKD. BY DLP

DATE

8-6-79

SHEET NO.

F OF M

Engineers • Geologists • Planners  
Environmental Specialists

## OVERTOPPING

DAM SAFETY INSPECTION  
CHERRY RUN DAM \*\*\*\*\* OVERTOPPING ANALYSIS \*\*\*\*\*  
15-MINUTE TIME STEP AND 48-HOUR STORM DURATION

NO 288  
NHR 0  
NMIN 15  
IDAY 0  
JUPER 5  
METRC 0  
LROPT 0  
TRACE 0

MULTI-PLAN ANALYSES TO BE PERFORMED

NPPLAN= 1 NRTIO= 3 LRTIO= 1

RTIO= .40

.50

1.00

## SUB-AREA RUNOFF COMPUTATION

INFLOW INTO CHERRY RUN DAM RESERVOIR

ISTAQ 1  
ICOMP 0  
IECON 0  
ITAPE 0  
JPLT 0  
JPRT 0  
JNAME 1  
JSTAGE 0  
JLAUTO 0

## HYDROGRAPH DATA

INIDG 1  
LONG 1  
TAREA 11.40  
SNAP 0.00  
TRSDA 11.40  
TRSPC 0.000  
RATIO 0.000  
ISNDR 0  
ISAME 1  
LOCAL 0

## PRECIP DATA

SPEE 0.00  
PMS 24.00  
R6 101.00  
R12 119.00  
R24 129.00  
R48 139.00  
R96 0.00

TRSPC COMPUTED BY THE PROGRAM IS .405

INITIAL AND CONSTANT FAULT LOSS

AS PER CSE

## LOSS DATA

LOOPT 0  
STRAK 0  
DLTAR 0.00  
HTIDL 1.00  
ERAIN 0.00  
STKRS 0.00  
RIIUK 1.00  
STRTL 1.00  
CHSTL .05  
ALSMX 0.00  
RTIMP 0.00

## UNIT HYDROGRAPH DATA

IP= 4.11 CP= .45 NIA= 0

BASE FLOW PARAMETERS

AS PER CSE

## RECESSION DATA

SIRTO= -1.50 GRCSM= -.05

APPROXIMATE CUNK COEFFICIENTS FROM GIVEN SNYDER CP AND IF ARE TC=17.13 AND H=26.16 INTERVALS

UNIT HYDROGRAPH 100 END-OF-PERIOD ORDINATES, LAG= 4.15 HOURS, CP= .45 VOL= .97

11.	42.	86.	140.	201.	267.	338.	412.	490.	564.
631.	689.	738.	777.	806.	824.	826.	809.	779.	750.
721.	694.	668.	643.	619.	596.	574.	552.	531.	511.
330.	312.	296.	279.	268.	257.	247.	237.	227.	217.
229.	212.	195.	178.	161.	144.	127.	110.	93.	76.
101.	84.	67.	50.	33.	16.	0.	0.	0.	0.
13.	10.	7.	4.	2.	1.	0.	0.	0.	0.
50.	44.	38.	32.	26.	20.	14.	8.	2.	0.



SUBJECT

DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJV

DATE

8-6-79

PROJ. NO.

73-617-273

CHKD. BY DLR

DATE

8-6-79

SHEET NO.

G OF M

Engineers • Geologists • Planners  
Environmental Specialists

MO. DA	HR. MN	PERIOD	RAIN	EXCS	LOSS	COMP U	MO. DA	HR. MN	PERIOD	RAIN	EXCS	LOSS	COMP U
FWD-UP-PERIOD FLOW													
INFLOWS													
INTO													
RESERVOIR													
TOTAL VOLUME													
PMF													
0.4 PMF													
0.5 PMF													

## HYDROGRAPH ROUTING

## ROUTE INFLOW THROUGH RESERVOIR

ROUTE	INFLOW	THROUGH	RESERVOIR	ROUTE	INFLOW	THROUGH	RESERVOIR
1ST AQ	101	1	0	1ST AQ	101	1	0
2ND AQ	101	1	0	2ND AQ	101	1	0
3RD AQ	101	1	0	3RD AQ	101	1	0
4TH AQ	101	1	0	4TH AQ	101	1	0
5TH AQ	101	1	0	5TH AQ	101	1	0
6TH AQ	101	1	0	6TH AQ	101	1	0
7TH AQ	101	1	0	7TH AQ	101	1	0
8TH AQ	101	1	0	8TH AQ	101	1	0
9TH AQ	101	1	0	9TH AQ	101	1	0
10TH AQ	101	1	0	10TH AQ	101	1	0
11TH AQ	101	1	0	11TH AQ	101	1	0
12TH AQ	101	1	0	12TH AQ	101	1	0
13TH AQ	101	1	0	13TH AQ	101	1	0
14TH AQ	101	1	0	14TH AQ	101	1	0
15TH AQ	101	1	0	15TH AQ	101	1	0
16TH AQ	101	1	0	16TH AQ	101	1	0
17TH AQ	101	1	0	17TH AQ	101	1	0
18TH AQ	101	1	0	18TH AQ	101	1	0
19TH AQ	101	1	0	19TH AQ	101	1	0
20TH AQ	101	1	0	20TH AQ	101	1	0
21TH AQ	101	1	0	21TH AQ	101	1	0
22TH AQ	101	1	0	22TH AQ	101	1	0
23TH AQ	101	1	0	23TH AQ	101	1	0
24TH AQ	101	1	0	24TH AQ	101	1	0
25TH AQ	101	1	0	25TH AQ	101	1	0
26TH AQ	101	1	0	26TH AQ	101	1	0
27TH AQ	101	1	0	27TH AQ	101	1	0
28TH AQ	101	1	0	28TH AQ	101	1	0
29TH AQ	101	1	0	29TH AQ	101	1	0
30TH AQ	101	1	0	30TH AQ	101	1	0
31TH AQ	101	1	0	31TH AQ	101	1	0
32TH AQ	101	1	0	32TH AQ	101	1	0
33TH AQ	101	1	0	33TH AQ	101	1	0
34TH AQ	101	1	0	34TH AQ	101	1	0
35TH AQ	101	1	0	35TH AQ	101	1	0
36TH AQ	101	1	0	36TH AQ	101	1	0
37TH AQ	101	1	0	37TH AQ	101	1	0
38TH AQ	101	1	0	38TH AQ	101	1	0
39TH AQ	101	1	0	39TH AQ	101	1	0
40TH AQ	101	1	0	40TH AQ	101	1	0
41TH AQ	101	1	0	41TH AQ	101	1	0
42TH AQ	101	1	0	42TH AQ	101	1	0
43TH AQ	101	1	0	43TH AQ	101	1	0
44TH AQ	101	1	0	44TH AQ	101	1	0
45TH AQ	101	1	0	45TH AQ	101	1	0
46TH AQ	101	1	0	46TH AQ	101	1	0
47TH AQ	101	1	0	47TH AQ	101	1	0
48TH AQ	101	1	0	48TH AQ	101	1	0
49TH AQ	101	1	0	49TH AQ	101	1	0
50TH AQ	101	1	0	50TH AQ	101	1	0
51TH AQ	101	1	0	51TH AQ	101	1	0
52TH AQ	101	1	0	52TH AQ	101	1	0
53TH AQ	101	1	0	53TH AQ	101	1	0
54TH AQ	101	1	0	54TH AQ	101	1	0
55TH AQ	101	1	0	55TH AQ	101	1	0
56TH AQ	101	1	0	56TH AQ	101	1	0
57TH AQ	101	1	0	57TH AQ	101	1	0
58TH AQ	101	1	0	58TH AQ	101	1	0
59TH AQ	101	1	0	59TH AQ	101	1	0
60TH AQ	101	1	0	60TH AQ	101	1	0
61TH AQ	101	1	0	61TH AQ	101	1	0
62TH AQ	101	1	0	62TH AQ	101	1	0
63TH AQ	101	1	0	63TH AQ	101	1	0
64TH AQ	101	1	0	64TH AQ	101	1	0
65TH AQ	101	1	0	65TH AQ	101	1	0
66TH AQ	101	1	0	66TH AQ	101	1	0
67TH AQ	101	1	0	67TH AQ	101	1	0
68TH AQ	101	1	0	68TH AQ	101	1	0
69TH AQ	101	1	0	69TH AQ	101	1	0
70TH AQ	101	1	0	70TH AQ	101	1	0
71TH AQ	101	1	0	71TH AQ	101	1	0
72TH AQ	101	1	0	72TH AQ	101	1	0
73TH AQ	101	1	0	73TH AQ	101	1	0
74TH AQ	101	1	0	74TH AQ	101	1	0
75TH AQ	101	1	0	75TH AQ	101	1	0
76TH AQ	101	1	0	76TH AQ	101	1	0
77TH AQ	101	1	0	77TH AQ	101	1	0
78TH AQ	101	1	0	78TH AQ	101	1	0
79TH AQ	101	1	0	79TH AQ	101	1	0
80TH AQ	101	1	0	80TH AQ	101	1	0
81TH AQ	101	1	0	81TH AQ	101	1	0
82TH AQ	101	1	0	82TH AQ	101	1	0
83TH AQ	101	1	0	83TH AQ	101	1	0
84TH AQ	101	1	0	84TH AQ	101	1	0
85TH AQ	101	1	0	85TH AQ	101	1	0
86TH AQ	101	1	0	86TH AQ	101	1	0
87TH AQ	101	1	0	87TH AQ	101	1	0
88TH AQ	101	1	0	88TH AQ	101	1	0
89TH AQ	101	1	0	89TH AQ	101	1	0
90TH AQ	101	1	0	90TH AQ	101	1	0
91TH AQ	101	1	0	91TH AQ	101	1	0
92TH AQ	101	1	0	92TH AQ	101	1	0
93TH AQ	101	1	0	93TH AQ	101	1	0
94TH AQ	101	1	0	94TH AQ	101	1	0
95TH AQ	101	1	0	95TH AQ	101	1	0
96TH AQ	101	1	0	96TH AQ	101	1	0
97TH AQ	101	1	0	97TH AQ	101	1	0
98TH AQ	101	1	0	98TH AQ	101	1	0
99TH AQ	101	1	0	99TH AQ	101	1	0
100TH AQ	101	1	0	100TH AQ	101	1	0

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-6-79 PROJ. NO. 79-617-278  
 CHKD. BY DLB DATE 8-6-79 SHEET NO. H OF M



CREST LENGTH AT OR BELOW ELEVATION	IABCUA				ISPITW				ISPCFW			
	10	10	10	10	10	10	10	10	10	10	10	10
1007.20	0.	0.	0.0	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1025.00	155.	0.	0.0	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1026.00	219.	434.	1008.1	434.	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1027.00	256	1316	1008.3	1316.	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1028.00	291.	2547.	1008.6	2547.	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1029.00	341.	4097.	1008.9	4097.	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1030.00	390.	5899.	1009.3	5899.	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1032.00	498.	9980.	1010.1	9980.	0.	0.0	0.0	0.0	0.0	0.0	0.0	0.0

DAM DATA	TOPEL				CROD				EXPD				DAMWID			
	1030.0	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0
25.	70.	105.	120.	195.	270.	305.	340.	375.	410.	445.	480.	515.	550.	585.	620.	655.
1030.0	1030.1	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0

PEAK OUTFLOW IS 14601. AT TIME 44.00 HOURS	CFS				CFS				CFS				CFS			
	1030.0	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0
1030.0	1030.1	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0

PEAK OUTFLOW IS 5816. AT TIME 44.00 HOURS	CFS				CFS				CFS				CFS			
	1030.0	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0
1030.0	1030.1	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0

PEAK OUTFLOW IS 1292. AT TIME 44.00 HOURS	CFS				CFS				CFS				CFS			
	1030.0	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0
1030.0	1030.1	1030.3	1030.4	1030.8	1030.9	1031.1	1032.0	1033.0	1034.0	1035.0	1036.0	1037.0	1038.0	1039.0	1040.0	1041.0

RESERVOIR  
 OUTFLOW  
 WINDING UP

SUBJECT

DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJV

DATE 8-6-79

PROJ. NO. 73-617-273

CHKD. BY DLB

DATE 8-6-79

SHEET NO. I OF M

Engineers • Geologists • Planners  
Environmental Specialists

## HYDROGRAPH ROUTING

ROUTE FROM DAM TO SECTION 2 \* 2640 FT DS FROM DAM

STORAGE	0.00	5.70	18.50	40.00	89.10	132.00	165.00	201.00	247.00
OUTFLOW	0.00	350.00	411.00	444.00	470.00	7600.00	10200.00	12700.00	17800.00
	0.00	400.00	1400.00	2500.00	5000.00	7600.00	10200.00	12700.00	17800.00
	28000.00	42000.00	40000.00	45000.00	49000.00	7600.00	10200.00	12700.00	17800.00

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
14591.	12283.	6002.	2432.	700343.
413.	348.	187.	69.	19832.
CFS	10.02	21.55	23.81	23.81
CMS	254.57	547.35	604.81	604.81
INCHES	6091.	13095.	14470.	14470.
MM	7513.	16153.	17848.	17848.
AC-FT				
THOUS CU M				

MAXIMUM STORAGE = 218.

HYDROGRAPHS

@ SECTION 2

@ 13' HOUSES

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
5802.	5069.	2641.	973.	280162.
164.	144.	75.	28.	7933.
CFS	4.14	8.62	9.53	9.53
CMS	105.05	218.92	241.95	241.95
INCHES	2513.	5238.	5788.	5788.
MM	3100.	6460.	7140.	7140.
AC-FT				
THOUS CU M				

MAXIMUM STORAGE = 102.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
7270.	6338.	3301.	1216.	350183.
206.	179.	93.	34.	9916.
CFS	5.17	10.77	11.91	11.91
CMS	131.36	273.64	302.42	302.42
INCHES	3143.	6547.	7235.	7235.
MM	3676.	8075.	8924.	8924.
AC-FT				
THOUS CU M				

MAXIMUM STORAGE = 127.

0.5 PMF

SUBJECT DAM SAFETY INSPECTION

CHERRY RUN DAM

Y WJV

DATE 8-6-79

PROJ. NO. 73-617-273

CHKD. BY DLB

DATE 8-6-79

SHEET NO. 1 OF M



Engineers • Geologists • Planners  
Environmental Specialists

HYDROGRAPH ROUTING

ROUTE FROM SECTION 2 TO SECTION 3 + 4000 FT DS FROM DAM

STAGE	0.00	3.00	10.30	28.50	74.90	106.00	129.00	145.00	175.00
STORAGE	229.00	251.00	298.00	327.00	349.00				
OUTFLOW	0.00	400.00	1400.00	2500.00	5000.00	7600.00	10200.00	12700.00	17800.00
	28000.00	32000.00	40000.00	45000.00	49000.00				

PEAK	145.72	143.	413.
CFS	14572.	143.	413.
CMS	14572.	143.	413.
INCHES	14572.	143.	413.
MM	14572.	143.	413.
AC-FT	14572.	143.	413.
THOUS CU M	14572.	143.	413.

PMF

HYDROGRAPHS

SECTION 3

SECTION 3

MAXIMUM STORAGE = 156.

PEAK	5790.	164.
CFS	5790.	164.
CMS	5790.	164.
INCHES	5790.	164.
MM	5790.	164.
AC-FT	5790.	164.
THOUS CU M	5790.	164.

0.4 PMF

MAXIMUM STORAGE = 84.

PEAK	1259.	206.
CFS	1259.	206.
CMS	1259.	206.
INCHES	1259.	206.
MM	1259.	206.
AC-FT	1259.	206.
THOUS CU M	1259.	206.

0.5 PMF

MAXIMUM STORAGE = 102.

PEAK	1259.	206.
CFS	1259.	206.
CMS	1259.	206.
INCHES	1259.	206.
MM	1259.	206.
AC-FT	1259.	206.
THOUS CU M	1259.	206.

SUBJECT DAM SAFETY INSPECTION

CHERRY RUN DAM

BY WJV DATE 8-6-79 PROJ. NO. 79-617-278

CHKD. BY DLB DATE 8-6-79 SHEET NO. K OF M



Engineers • Geologists • Planners  
Environmental Specialists

SUMMARY OF DAM SAFETY ANALYSIS

	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1025.00 185. 0.	SPILLWAY CREST 1025.00 185. 0.	TOP OF DAM 1030.00 390. 5899.
RATIO OF PAF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS
.40	1029.95	0.00	388.	5816.
.50	1030.62	.62	422.	7292.
1.00	1033.01	3.01	561.	14601.
			DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS
			0.00	44.00
			4.00	44.00
			11.75	44.00
				TIME OF FAILURE HOURS
				0.00
				0.00
				0.00

SECTION 2	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT
RATIO		**
0.4	5802	1013.4
0.5	7270	1014.4
1.0	14591	1017.3

@ 1st  
TWO HOUSES

SECTION 3	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT
RATIO		**
0.4	5790	1012.0
0.5	7259	1013.0
1.0	14572	1015.1

@ 2nd  
HOUSE AND  
1st BRIDGE

\* FLOWS OBTAINED FROM DETAILED HEC-1 OUTPUT  
\*\* FLOW RATIOS INTERPOLATED FROM SAFETY D AND E



SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-6-79 PROJ. NO. 78-617-278  
 CHKD. BY DLB DATE 8-6-79 SHEET NO. L OF M



Engineers • Geologists • Planners  
 Environmental Specialists

BREACHING ANALYSTS  
 CONSISTS OF SAME INPUT  
 DATA AS FOR THE  
 OVERTOPPING ANALYSIS  
 W/ THE ADDITION OF THE  
 BREACH DATA  
 GIVEN HERE

## BREACHING

DAM SAFETY INSPECTION  
 CHERRY RUN DAM \*\*\*\*\*  
 15-MINUTE TIME STEP AND 48-HOUR STORM DURATION

JOB SPECIFICATION  
 NO. HIR NMIN IDAY IHR IMIN METHC IPLT IPRT NSTAN  
 288 0 15 0 0 0 0 -4 0  
 JUPER NWI LRUPT TRACE  
 5 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED  
 NPLAN= 6 NNTIU= 1 LNTIU= 1

NFIUS= .41

### HYDROGRAPH ROUTING

ROUTE INFLOW THROUGH RESERVOIR

PLAN

DAM DATA  
 TOPEL 1030.0  
 COND 0.0  
 EXPD 0.0  
 DAMWD 0.

DAM BREACH DATA  
 Z 1.00  
 ELBM 1012.00  
 TFAIL .50  
 WSEL 1025.00  
 WSEL FAILED 1030.00

BEGIN DAM FAILURE AT 43.75 HOURS

PEAK OUTFLOW IS 8032. AT TIME 44.25 HOURS

DAM BREACH DATA  
 Z 3.00  
 ELBM 1012.00  
 TFAIL .50  
 WSEL 1025.00  
 WSEL FAILED 1030.00

BEGIN DAM FAILURE AT 43.75 HOURS

PEAK OUTFLOW IS 18410. AT TIME 44.11 HOURS

DAM BREACH DATA  
 Z 1.00  
 ELBM 1012.00  
 TFAIL 4.00  
 WSEL 1025.00  
 WSEL FAILED 1030.00

BEGIN DAM FAILURE AT 43.75 HOURS

PEAK OUTFLOW IS 5967. AT TIME 44.08 HOURS

(1)

(2)

(3)

\* PLAN NUMBER ① ② ③ ④ ⑤ ⑥

SUBJECT DAM SAFETY INSPECTION  
CHERRY RUN DAM  
 BY WJV DATE 8-6-79 PROJ. NO. 78-617-278  
 CHKD. BY DLB DATE 8-6-79 SHEET NO. M OF M



PLAN

DAM BREACH DATA  
 Z ELUM TFAIL WSEL FAILED  
 3.00 1012.00 4.00 1025.00 1030.00

HRWID  
 300.

BEGIN DAM FAILURE AT 43.75 HOURS

PEAK OUTFLOW IS 7213. AT TIME 44.58 HOURS

④

DAM BREACH DATA  
 Z ELUM TFAIL WSEL FAILED  
 1.00 1012.00 1.00 1025.00 1030.00

HRWID  
 150.

BEGIN DAM FAILURE AT 43.75 HOURS

PEAK OUTFLOW IS 11628. AT TIME 44.56 HOURS

⑤

DAM BREACH DATA  
 Z ELUM TFAIL WSEL FAILED  
 1.00 1012.00 .75 1025.00 1030.00

HRWID  
 100.

BEGIN DAM FAILURE AT 43.75 HOURS

PEAK OUTFLOW IS 20722. AT TIME 44.00 HOURS

⑥

SUMMARY OF DAM SAFETY ANALYSIS

PLAN	RATIO OF PMF	MAXIMUM RESERVOIR M.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0	.41	1030.02	.02	391.	8032.	.45	44.25	43.75
②	.41	1030.01	.01	391.	18410.	.27	44.11	43.75
③	.41	1030.03	.03	391.	5967.	.83	44.08	43.75
④	.41	1030.01	.01	391.	7213.	.33	44.58	43.75
⑤	.41	1030.02	.02	391.	11628.	.29	44.56	43.75
⑥	.41	1030.02	.02	391.	20722.	.28	44.00	43.75

NOTE: SEE SHEET 15 OF 15 FOR DOWNSTREAM ROUTING SUMMARY

PLAN NUMBER ① ② ③ ④ ⑤ ⑥

## LIST OF REFERENCES

1. "Recommended Guidelines for Safety Inspection of Dams," prepared by Department of the Army Office of the Chief of Engineers, Washington, D. C. (Appendix D).
2. "Unit Hydrograph Concepts and Calculations," by Corps of Engineers, Baltimore District (L-519).
3. "Seasonal Variation of Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24, and 48 Hours," Hydrometeorological Report No. 33, prepared by J. T. Riedel, J. F. Appleby and R. W. Schloemer Hydrologic Service Division Hydrometeorological Section, U. S. Department of the Army, Corps of Engineers, Washington, D. C., April 1956.
4. Design of Small Dams, U. S. Department of the Interior, Bureau of Reclamation, Washington, D. C., 1973.
5. Handbook of Hydraulic, H. W. King and E. F. Brater, McGraw-Hill, Inc., New York, 1963.
6. Standard Handbook for Civil Engineers, F. S. Merritt McGraw-Hill, Inc., New York, 1968.
7. Open-Channel Hydraulics, V. T. Chow, McGraw-Hill, Inc., New York, 1959.
8. Weir Experiments, Coefficients, and Formulas, R. E. Horton, Water Supply and Irrigation Paper No. 200, Department of the Interior, United States Geological Survey, Washington, D. C., 1907.
9. "Probable Maximum Precipitation Susquehanna River Drainage Above Harrisburg, Pennsylvania," Hydrometeorological Report 40, prepared by H. V. Goodyear and J. T. Riedel, Hydrometeorological Branch Office of Hydrology, U. S. Weather Bureau, U. S. Department of Commerce, Washington, D. C., May 1965.
10. Flood Hydrograph Package (HEC-1) Dam Safety Version, Hydrologic Engineering Center, U. S. Army Corps of Engineers, Davis, California, July 1978.
11. "Simulation of Flow Through Broad Crest Navigation Dams with Radial Gates," R. W. Schmitt, U. S. Army Corps of Engineers, Pittsburgh District.

12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.
13. Applied Hydraulics in Engineering, Morris, Henry M. and Wiggert, James N., Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
14. Standard Mathematical Tables, 21st Edition, The Chemical Rubber Company, 1973, page 15.
15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C. 1969.

X1	3.00	X1	2.98	X1	1.00
X2	6.0	X2	0.1	GK	1040.00
X3	10.00			GK	1007.00
X4	10.00			NC	0.1
X5	10.00				
X6	1030.00				
X7	1011.00				
X8	1040.00				
X9	0.0				

SECTION  
 @  
 2 100 FT  
 DS FROM  
 DAM

APPENDIX D  
 PHOTOGRAPHS



PHOTOGRAPH 1 View of the downstream embankment face as seen from the left abutment.

PHOTOGRAPH 2 View of the upstream embankment face to the left of the spillway.


PHOTOGRAPH 3 View of the reservoir behind Cherry Run Dam as seen from the embankment crest. The structure in the center of the view is what remains of the control tower. Note the deteriorated condition of the access footbridge.

PHOTOGRAPH 4 View of the interior of the control tower that formerly housed all of the valving mechanisms for the outlet works.

SECTION  
@  
2 6000  
DS FLOW  
DAM

SECTION  
@  
2 5000  
DS FLOW  
DAM

SECTION  
@  
2 5000  
DS FLOW  
(LOCAL FLOW)  
2 4000 F  
FROM DAM




1



2



3



4

DS  
FACE  
OF  
BRIDGE

US FACE  
OF BRIDGE  
@ 2ND  
STRUCTURE  
LOCATION

SECTION  
@  
25 FT US  
FROM BRIDGE  
(OR 315 FT  
DS FROM  
DAM)

PHOTOGRAPH 5

View of the discharge end of the 24-inch diameter C.I.P. blowoff located to the left of the spillway about 75 feet downstream of the embankment.

PHOTOGRAPH 6

View of the discharge end of the 80-foot terra-cotta extension of the blowoff conduit.

PHOTOGRAPH 7

View of the dilapidated pump house located downstream of the embankment.

PHOTOGRAPH 8


View of the spillway as seen from atop the left wingwall.

SECTION  
@ 26.45 FT  
D> FROM  
DAM  
@ 1st  
STRUCTURE  
LOCATION

DS  
THE  
OF  
DAM



6



8



5



7

PHOTOGRAPH 9

View of the deteriorated left wingwall of the spillway. Note the extensive cracking, spalling, and efflorescence.

PHOTOGRAPH 10

Close-up view of the left wingwall of the spillway. Note the outward bow in the center portion of the wall and the spalling near the top.

PHOTOGRAPH 11

View of the heavily overgrown spillway discharge channel.

PHOTOGRAPH 12

View of a bridge and low lying house located less than one mile downstream of the embankment.

U  
MILWAUKEE

INFLOW

INLET


RESERVOIR

SURFACE

CAP

EFFLUENT





9



10



11



12

APPENDIX E

GEOLOGY

### Geology\*


Cherry Run Dam is located in the Pittsburgh Plateaus Section of the Appalachian Plateaus Physiographic Province. The Pittsburgh Plateaus Section is characterized by flat lying to gently folded sedimentary rock strata of Pennsylvania age. Major structural axes strike from southwest to northeast with the rock strata generally dipping northwest and southeast. The amplitude of folding in this section is quite low, consequently, surface expression of the anticlinal axes is not evident.

Cherry Run Dam and reservoir are located approximately one mile west of Homer City on Cherry Run, a tributary of Two Lick Creek. Structurally, the dam lies just west of the axial trace of the Latrobe syncline. Rock strata underlying the dam and reservoir, therefore, dip to the southeast at approximately 133 feet per mile or about one degree.

The dam and reservoir are located on sedimentary rock strata of the Conemaugh Group of Pennsylvanian age. The embankment is constructed on bedrock of the lower half of the Conemaugh group. This section of the Conemaugh consists of interbedded sandstones, a few thin limestones and minor coal beds.

---

\*Indiana Folio, Pennsylvania, U. S. Geological Survey, No. 102, 1904.





APPENDIX F

FIGURES



# LIST OF FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	General Plan - Field Inspection Notes
2	Cross-section Through Dam and Gate House
3	Cross-section Through Spillway
4	Plan of Spillway
5	Piping Layout Below Spillway
6	Pump Station Layout
7	Valley Section Along Centerline of Cherry Run Dam






FIGURE 1 - CHERRY RUN DAM  
GENERAL PLAN : FIELD INSPECTION NOTES



















PLAN VIEW OF SPILLWAY





REQUIRED LIST		
No.	SIZE	REMARKS
5	Res. 12" B+S.C.T. Pipe 12'-0"	Furnished by Lucerne
1	12" 12" x 12" Flg Tee	Std. Drill, Ordered
1	12" 45° Flg Tee	Std. Drill, Ordered
1	Pc. 12" C.T. B+S Flg. to lay 12"	Ordered
2	12" 45° B+S Bend	Ordered
1	Pc. 12" C.T. Pipe 54.5	On hand at C.R.
1	12" Blank Flg.	Std. Drill
1	6" Comp. Flg. Threaded for 6" W.I. Pipe	Std. Drill
1	Std. 12" Gate Valv. Flg.	Std. Drill, Ord.
5	Red Rubber Gaskets 12" 12" 12"	12" Pipe
1	Red Rubber Gasket 8 1/2" 8 1/2" 8 1/2"	6" Comp. Flg.
60	Bolts 7/8 dia x 3 1/2" Lg.	
8	Bolts 3/4 dia x 3" Lg.	

Layout of Pump Connection  
Scale 1/8" = 1'-0"



cut channel to be filled and leveled for seeding

edge of cut 12' from edge of concrete

74.80' of 24" Concrete Pipe on any 2' in minimum. If conditions are found make it necessary should be attended further

Cut to

Layout

AD-A078 867

GAI CONSULTANTS INC MONROEVILLE PA

NATIONAL DAM INSPECTION PROGRAM. CHERRY RUN DAM (NDS I.D. NUMBE--ETC(U)

AUG 79 B M MIHALCIN

F/G 13/13  
DACW31-79-C-0013

NL

UNCLASSIFIED


2 OF 2

AD  
A 078867



END  
DATE  
FILMED  
1-80  
DOC





MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

Present Channel

edge of cut 2

Cut to start at elev 1009.

elev top of wall 1008

Apron

Layout of Cut Below Spillway  
Scale 1"=20'


Revised Oct 25<sup>th</sup> 1923  
 ENGINEERING & SURVEYING CO. INC.  
 Engineering Dept. - Baltimore, Md.  
 Cut and Piping  
 Below Spillway  
 Cherry Run Dam  
 by Luster  
 by Luster  
 and Re noted  
 E 3789

FIGURE 5














6

APPENDIX G

REGIONAL VICINITY  
AND  
WATERSHED BOUNDARY MAPS

0

